

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS


Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/DLP-081

1. Name	SECTION I : IDENTIFICATION		
Present Past Other Name (if any): 2. Location	: Manohar Vishramalay :		
LONGITUDE 78 ⁰ 17 ['] E	LATITUDE 27 ⁰ 50 [°] N		
Address	Machkund, Dhaulpur		
	: Village (village code) Post : Dhaulpur District: Dhaulpur State : Rajasthan PIN: 328001		
Approach	 The Building is situated at Machkund in Dhaulpur. It is 4 k.m. away from Dhaulpur city bus stand. It is well connected by regular bus services. 		

3. Property Type



4. Property Use

	ABANDONED / IN USE : Abandoned
Present Past	:
5. Age (Source)	
PERIOD	: 18 th Century A.D.
YEARS	:
Precise date of Construction	:
Completion	:
Subsequent changes	:
Destruction / Demolition	:
6. Ownership / Level of Protection	on
	SINGLE /MULTIPLE :
Public : Archaeological Survey of	:
India / State Archaeology	
Department / Any Other (Please	
specify)	
Private	:
Any other (Please specify)	:
Name	
Address Phone	· · · · · · · · · · · · · · · · · · ·
FIIONE	•
7. Association	
WITH EVENTS	
In History	: Vishramalay
In Rituals	:
In Building Construction	:
Any other (specify)	:
WITH PERSONS	
Patron	
Architect / Engineer Any other (specify)	· · · · · · · · · · · · · · · · · · ·
Any other (specify)	•
8. Statement of Significance	
Architectural	Pillar with capital
Archaeological	· ····· · ···· · · ····
Historical	
Religious	
Any other (specify)	

SECTION II: DESCRIPTION

9.	9. Physical Description and Decorative Features					
•	Context Urban / Rural Setting Surroundings		 * Drawings (Attach extra sheet if necessary) Rural Setting Stand in Isolation Integral part of a Landscape / Street / Complex 			
•	Quantification Area Dimension (L x B x H) Number of Blocks Number of Storys	:	(m / cm/ feet / inch) 02			
•	Spatial Organization Orientation Plan Allocation of Spaces	:	The Building is oriented East-West and faces the West			
•	RCHITECTURAL STYLE Ornamentation Exteriors Interiors Movable Collections ny Other (specify)	:	Pillars with capital, foliated arch			

10. Construction Technology

Structural System Building Techniques	:	Indo-Persian Arcuate system
Material of Construction	:	Stone and plaster

11. Condition Assessment

In General

Good / Fair

Fair

Sign of Deterioration Serious Deterioration Danger of Disappearance

In Brief (Attach extra sheet if necessary):

Dust and Dirt Deposition, Blackening of surface, Breaking of structure

12. Threats to the Property

Natural Negligence Vandalism Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS