

**INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS** 

Janpath, New Delhi -110 001, www.ignca.gov.in

## Documentation format for Archaeological / Heritage Sites / Monuments

#### Serial No.: RJ/DLP-168

SECTION I: IDENTIFICATION		
1. Name		
Present Past Other Name (if any):	Court Gate	
2. Location		
LONGITUDE 78° 17 <sup>°</sup> E	<b>LATITUDE</b> 27 <sup>0</sup> 50 <sup>°</sup> N	
Address	Tahsil Bari, Dhaulpur	
Approach	<ul> <li>: Village (village code) Post : Bari District: Dhaulpur State : Rajasthan PIN: 328021</li> <li>: The Gateway is situated at Bari in Dhaulpur. It is 34 Km away from Dhaulpur. It is well connected by regular bus services.</li> </ul>	

### 3. Property Type

court. It . It is a
of the
l with
l O

## 4. Property Use

		ABANDONED / IN USE :
Present	_	
Present Past		
Past	•	
5. Age (Source)		
PERIOD	_	
PERIOD YEARS		
Precise date of Construction		
Completion		
Subsequent changes	:	
Destruction / Demolition	:	
Destruction / Demonition	•	
6. Ownership / Level of Protection	on	
		SINGLE /MULTIPLE :
Public : Archaeological Survey of	:	
India / State Archaeology		
Department / Any Other (Please		
specify)		
Private	:	
Any other (Please specify)	:	
Name	:	
Address	:	
Phone	:	
7. Association		
WITH EVENTS		
In History	:	
In Rituals	:	
In Building Construction	:	
Any other (specify)	:	Gateway
WITH PERSONS		
Patron	:	
Architect / Engineer	:	
Any other (specify)	:	
8. Statement of Significance		
Architectural		
Archaeological		
Historical		

Religious Any other (specify)

Pointed arch

# **SECTION II: DESCRIPTION**

9.	9. Physical Description and Decorative Features		
•	Context Urban / Rural Setting Surroundings		* Drawings (Attach extra sheet if necessary)
	Jan 199		Stand in Isolation Integral part of a Landscape / Street / Complex
•	<b>Quantification</b> Area Dimension ( L x B x H)	:	(m/cm/foot/inch)
	Number of Blocks Number of Storys	:	(m / cm/ feet / inch)
•	<b>Spatial Organization</b> Orientation Plan Allocation of Spaces	: : :	
•	<b>CHITECTURAL STYLE</b> Ornamentation Exteriors Interiors Movable Collections by Other (specify)	:	Pointed arch, medallion
10	. Construction Technology		
	Ctrusturel Custom		la de Develor

Structural System	:	Indo Persian
Building Techniques	:	Arcuate system
Material of Construction	:	Red Stone and Plaster

#### 11. Condition Assessment

In General	Good / Fair	
	Good	

Sign of Deterioration Serious Deterioration Danger of Disappearance

### In Brief (Attach extra sheet if necessary):

Blackening of surface.

## 12. Threats to the Property

Natural Negligence Vandalism Urban Pressures

# SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS