


INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/DLP-200

	SECTION L: IDENTIFICATION
1. Name	
Present Past Other Name (if any):	: Lodi Wanshi Bawari :
2. Location	
LONGITUDE 78° 17 [°] E	LATITUDE 27 [°] 50 [°] N
Address	Bari, Dhaulpur
	: Village (village code) Post : Bari District: Dhaulpur State : Rajasthan PIN: 328021
Approach	: The Bawari is situated at Bari in Dhaulpur. It is 36 Km away from Dhaulpur bus stand. It is well connected by regular bus services.
3. Property Type	



4. Property Use

		ABANDONED / IN USE :	Abandoned
Present	:		
Past	:		
5. Age (Source)			
PERIOD	:	18 th century AD	
YEARS	:		
Precise date of Construction	:		
Completion	:		
Subsequent changes	:		
Destruction / Demolition	:		
6. Ownership / Level of Protection	on		
		SINGLE /MULTIPLE :	
Public : Archaeological Survey of	:		
India / State Archaeology			
Department / Any Other (Please			
specify)			
Private	:		
Any other (Please specify)	:		
Name	:		
Address	:		
Phone	:		
7. Association			
WITH EVENTS			
In History	:		
In Rituals	:		
In Building Construction	:		
Any other (specify)	:	Water reservoir	
WITH PERSONS			
Patron	:		
Architect / Engineer	:		
Any other (specify)	:		
8. Statement of Significance			
Architectural			
Archaeological			
Historical Religious			
I VEIIUUUS			

Religious Any other (specify)

Square shaped

SECTION II: DESCRIPTION

9.	9. Physical Description and Decorative Features		
•	Context Urban / Rural Setting Surroundings		* Drawings (Attach extra sheet if necessary) Urban Stand in Isolation Integral part of a Landscape / Street / Complex
•	Quantification Area Dimension (L x B x H) Number of Blocks Number of Storys	:	(m / cm/ feet / inch) 04
•	Spatial Organization Orientation Plan Allocation of Spaces	:	The Bawari is oriented East – West and faces the East.
•	RCHITECTURAL STYLE Ornamentation Exteriors Interiors Movable Collections Ny Other (specify)	:	

10. Construction Technology

Structural System Building Techniques	:	Arcuate system
Material of Construction	:	Stone and Plaster

11. Condition Assessment

In General

Good / Fair

Fair

Sign of Deterioration Serious Deterioration Danger of Disappearance

In Brief (Attach extra sheet if necessary):

Dust and Dirt Deposition, vegetation growth.

12. Threats to the Property

Natural Negligence Vandalism Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS