



INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/DLP-207

SECTION I : IDENTIFICATION

1. Name

Present : Qazi House
Past :
Other Name (if any): :

2. Location

LONGITUDE 78° 17' E

LATITUDE 27° 50' N

Address

Qazi House, Talab shahi, Bari

: **Village (village code)**

Post : Bari

District: Dhaulpur

State : Rajasthan

PIN: 328021

Approach

: The Qazi House is situated at Bari in Dhaulpur. It is 36 km. away from Dhaulpur bus stand. It is well connected by regular bus services.

3. Property Type

Buildings

- | | |
|-------------------------------------|------------------------|
| <input type="checkbox"/> | Palace |
| <input type="checkbox"/> | Fort |
| <input type="checkbox"/> | Citadel |
| <input type="checkbox"/> | Govt. building |
| <input type="checkbox"/> | Railway station |
| <input type="checkbox"/> | Defence building |
| <input type="checkbox"/> | Industrial building |
| <input checked="" type="checkbox"/> | Other public buildings |
| <input type="checkbox"/> | Residential building |

Religious structures

- | | |
|--------------------------|-----------------|
| <input type="checkbox"/> | Temple |
| <input type="checkbox"/> | Mosque |
| <input type="checkbox"/> | Minar |
| <input type="checkbox"/> | Church |
| <input type="checkbox"/> | Monastery |
| <input type="checkbox"/> | Stupa |
| <input type="checkbox"/> | Tomb, Mausoleum |

Other Structures

- | | |
|--------------------------|------------------|
| <input type="checkbox"/> | Wall |
| <input type="checkbox"/> | Gateway |
| <input type="checkbox"/> | Pillar |
| <input type="checkbox"/> | Others (specify) |

Engineering structure

- | | |
|--------------------------|-----------------------------|
| <input type="checkbox"/> | Bridge |
| <input type="checkbox"/> | Tunnel |
| <input type="checkbox"/> | Other engineering structure |

Open space and related structures

- | | |
|--------------------------|----------------|
| <input type="checkbox"/> | Public square |
| <input type="checkbox"/> | Park or garden |
| <input type="checkbox"/> | Graveyard |
| <input type="checkbox"/> | Baolis, Well |
| <input type="checkbox"/> | Tank |
| <input type="checkbox"/> | Cave |

Note: This is the Qazi house. It is made upon elevated platform. It has pointed arch opening. Building has decorated drum and below drum there is chajja. Supported by brackets.

4. Property Use

ABANDONED / IN USE : Abandoned

Present : Base of Rajasthan Police
Past : Court

5. Age (Source)

PERIOD : 18th Century A.D.
YEARS :
Precise date of Construction :
Completion :
Subsequent changes :
Destruction / Demolition :

6. Ownership / Level of Protection

SINGLE /MULTIPLE :

Public : Archaeological Survey of India / State Archaeology Department / Any Other (Please specify) : State Archaeology Department
Private :
Any other (Please specify) :
Name :
Address :
Phone :

7. Association

- **WITH EVENTS**
 - In History** :
 - In Rituals** :
 - In Building Construction** : House
 - Any other (specify)** :
- **WITH PERSONS**
 - Patron** :
 - Architect / Engineer** :
 - Any other (specify)** :

8. Statement of Significance

<input type="checkbox"/>	Architectural	Pointed arch
<input type="checkbox"/>	Archaeological	
<input type="checkbox"/>	Historical	
<input type="checkbox"/>	Religious	
<input type="checkbox"/>	Any other (specify)	

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features

- **Context** : * **Drawings** (Attach extra sheet if necessary)
Urban / Rural Setting
Surroundings : **Stand in Isolation**
Integral part of a Landscape / Street / Complex

- **Quantification**
Area Dimension (L x B x H) : (m / cm/ feet / inch)

Number of Blocks : 01
Number of Storys : 01

- **Spatial Organization**
Orientation : The Qazi House is oriented to the South
Plan :
Allocation of Spaces :

ARCHITECTURAL STYLE

- **Ornamentation**
Exteriors : Pointed arch
Interiors :
Movable Collections :
Any Other (specify) :

10. Construction Technology

- Structural System** : Indo-Persian
- Building Techniques** : Arcuate system
- Material of Construction** : Stone & Plaster

11. Condition Assessment

In General	Good / Fair
	Good

- | | |
|-------------------------------------|-------------------------|
| <input type="checkbox"/> | Sign of Deterioration |
| <input checked="" type="checkbox"/> | Serious Deterioration |
| <input type="checkbox"/> | Danger of Disappearance |

In Brief (Attach extra sheet if necessary):

Blackening of surface, vegetation growth, dust deposition.

12. Threats to the Property

- Natural
- Negligence
- Vandalism
- Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs

(attach list as in page 6, in case of multiple photographs)

Photo Reference

CAPTION

15. Audio / Video

(related to rituals / performance / festivals etc.)

Reference

DESCRIPTION

16. Maps/Plans/Drawings

17. Listers

NAME

NAME

18. Reviewers

NAME

NAME

COMMENTS

COMMENTS