

Past

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/DLP-212 **SECTION I: IDENTIFICATION** 1. Name Present Chaajju Ram ki chhatri Other Name (if any): 2. Location 27⁰ 50' N LONGITUDE 78° 17' E LATITUDE **Address** Talab shahi, Bari Village (village code) Post: Bari District: Dhaulpur State: Rajasthan **PIN**: 328021 Approach The Chattri is situated at Bari. It is 36 km. away from Dhaulpur. It is well connected by bus services. 3. Property Type **Buildings** Religious structures **Other Structures** Palace Temple Wall Mosque Fort Gateway Citadel Minar Pillar Others (specify) Govt. building Church Railway station Monastery Canapy Defence building Stupa Industrial building Tomb, Mausoleum Other public buildings Residential building Engineering structure Open space and related Note: This is the chhatri of structures Chaaiu Ram and is made upon Bridge Public square elevated platform. It is deomical Park or garden superstructure. Below drum there Tunnel is chajja which is supported by Other engineering structure Graveyard brackets. Chhatri has pointed arch

openings.

Baolis, Well

Tank Cave

| 4. Property Use | | |
|---|---|-------------------------------|
| | | ABANDONED / IN USE: Abandoned |
| Present Past | : | Memorial Memorial |
| 5. Age (Source) | | |
| PERIOD YEARS Precise date of Construction Completion Subsequent changes Destruction / Demolition | : : : : | 18 th Century A.D. |
| 6. Ownership / Level of Protection | On | SINGLE /MULTIPLE : |
| Public: Archaeological Survey of India / State Archaeology Department / Any Other (Please specify) Private Any other (Please specify) Name Address Phone | : | State Archaeology Department |
| WITH EVENTS In History In Rituals In Building Construction Any other (specify) WITH PERSONS Patron Architect / Engineer Any other (specify) 8. Statement of Significance | : | Chhatri |
| Architectural Archaeological Historical Religious Any other (specify) | Ca | nopied chhatri |

SECTION II: DESCRIPTION

| 9. | 9. Physical Description and Decorative Features | | | | | |
|----------|---|---|---|--|--|--|
| • | Context Urban / Rural Setting Surroundings | | * Drawings (Attach extra sheet if necessary) Rural setting | | | |
| | | | Stand in Isolation Integral part of a Landscape / Street / Complex | | | |
| • | Quantification Area Dimension (L x B x F | l) : | (m / cm/ feet / inch) | | | |
| | Number of Blocks Number of Storys | : | (III7 CIII/ leet 7 IIICII) | | | |
| • | Spatial Organization Orientation Plan Allocation of Spaces | : : : | The Chattri is oriented to North direction | | | |
| • | CHITECTURAL STYLE Ornamentation Exteriors Interiors Movable Collections y Other (specify) | : | Canopied chhatri, pointed arch | | | |
| 10. | Construction Technology | <i>'</i> | | | | |
| | Structural System Building Techniques Material of Construction | : : | Indo-Persian Arcuate system Stone and plaster | | | |
| 11. | Condition Assessment | | | | | |
| | | Good Good | / Fair | | | |
| ✓ | Sign of Deterioration Serious Deterioration Danger of Disappearance | : | | | | |
| In | Brief (Attach extra sheet if | neces | ssary): | | | |

Blackening of surface, dirt and dust deposition, breaking down of structure.

| 12. Threats to the Property | |
|-----------------------------|--|
| | Natural Negligence Vandalism Urban Pressures |

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

| 14. Photographs | |
|-------------------------|---|
| | (attach list as in page 6, in case of multiple photographs) |
| Photo Reference | |
| CAPTION | |
| 15. Audio / Video | |
| | (related to rituals / performance / festivals etc.) |
| Reference | |
| DESCRIPTION | |
| 16. Maps/Plans/Drawings | |
| | |
| | |
| 17. Listers | |
| NAME | NAME |
| 18. Reviewers | |
| NAME | NAME |
| COMMENTS | COMMENTS |