

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS


Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/DLP-217

1. Name	SECTION I : IDENTIFICATION
Present Past Other Name (if any): 2. Location	: Bhootaha Mahal :
LONGITUDE 78 ⁰ 17 ['] E	LATITUDE 27 ⁰ 50 [°] N
Address	Talab Shahi, Bari
	: Village (village code) Post : Bari District: Dhaulpur State : Rajasthan PIN: 328021
Approach	: The Talab Shahi Bhootaha Mahal is situated at Bari in Dhaulpur district. It is 36 km. away from Dhaulpur. It is well connected by bus services.

3. Property Type



4. Property Use ABANDONED / IN USE : Abandoned Present Palace 2 Palace Past • 5. Age (Source) 18th Century A.D. PERIOD 2 YEARS 2 Precise date of Construction 2 Completion : Subsequent changes : **Destruction / Demolition** : 6. Ownership / Level of Protection SINGLE /MULTIPLE : **Public** : Archaeological Survey of : State Archaeology Department India / State Archaeology Department / Any Other (Please specify) Private 2 Any other (Please specify) : Name : Address : Phone ÷ 7. Association WITH EVENTS In History : In Rituals : In Building Construction : Any other (specify) Mahal : WITH PERSONS Patron : **Architect / Engineer** 2 Any other (specify) : 8. Statement of Significance Architectural Canopied chhatri

Archaeological Historical Religious Any other (specify)

SECTION II: DESCRIPTION

Context		* Drawings (Attach ovtra choot if pococcary)				
•	Context Urban / Rural Setting		* Drawings (Attach extra sheet if necessary) Rural setting			
	Surroundings		Stand in Isolation Integral part of a Landscape / Street / Complex			
•	Quantification Area Dimension (L x B x H)	:	(m / cm/ feet / inch)			
	Number of Blocks Number of Storys	:	01 01			
•	Spatial Organization Orientation Plan Allocation of Spaces	:	The Palace is oriented North-South and faces North			
•	CHITECTURAL STYLE Ornamentation Exteriors Interiors Movable Collections by Other (specify)	: : : : : : : : : : : : : : : : : : : :	Domical, foliated arch			

10. Construction Technology

Structural System Building Techniques	:	Indo-Persian Arcuate system
Material of Construction	:	Stone and plaster

11. Condition Assessment

In General

Good / Fair Good

Sign of Deterioration Serious Deterioration Danger of Disappearance

In Brief (Attach extra sheet if necessary):

Blackening of surface, plaster peeling off, dirt and dust deposition.

12. Threats to the Property

Natural Negligence Vandalism Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS