


Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.:RJ/Dp-017

SECTION I: IDENTIFICATION

1. Name	
Present Past Other Name (if any):	Somanath Mandir Ka Gateway
2. Location	
LONGITUDE 74 ⁰ 23'E	LATITUDE 24 ⁰ 01 ['] N
Address	Near Dev Somnath Mandir, Dungarpur
	: Village (village code) Post: Dungarpur State: Rajasthan PIN: 314001
Approach district	 The Gateway is situated near by Dev Somnath Mandir in Dungarpur district. It is 25km away from Duganpur bus stand. It is well connected by regular bus services.

3. Property Type



4. Property Use

ABANDONED / IN USE $\sqrt{}$

SINGLE /MULTIPLE :

Present	:	Gateway
Past	:	Gateway

5. Age (Source)

PERIOD	:	17 th Century AD
YEARS	:	
Precise date of Construction	:	
Completion	:	
Subsequent changes	:	
Destruction / Demolition	:	

6. Ownership / Level of Protection

Public : Archaeological Survey of India / State Archaeology Department / Any Other (Please specify)state Govt.	:
Private	:
Any other (Please specify)	:
Name	:
Address	:
Phone	:

7. Association

•1 WITH EVENTS

In History	:
In Rituals	:
In Building Construction	:
Any other (specify)	:
•2 WITH PERSONS	
Patron	:
Architect / Engineer	:
Any other (specify)	:

8. Statement of Significance



Archaeological Historical

Gateway having carved pillars.

Religious Any other (specify)

:

SECTION II: DESCRIPTION

9. Physical Description and De	cor	ative Features
•3 Context Urban √/ Rural Setting Surroundings		* Drawings (Attach extra sheet if necessary)
		Stand in Isolation Integral part of a Landscape / Street / Complex
•4 Quantification		
Area Dimension (L x B x H)	:	<i>, , ,,</i> ,,, ,,
Number of Blocks		(m / cm/ feet / inch)
Number of Storys	:	
 5 Spatial Organization 		
Orientation	:	The Gateway is oriented East/West and faces the East.
Plan Allocation of Spaces	:	
ARCHITECTURAL STYLE		
•6 Ornamentation Exteriors		
Interiors	:	
Movable Collections	:	
Any Other (specify)	:	
10. Construction Technology		
Structural System Building Techniques Material of Construction	:	Gateway made up of stone.
	:	Stone, lime plaster

11. Condition Assessment

In General

Good√ / Fair

Sign of Deterioration Serious Deterioration Danger of Disappearance

In Brief (Attach extra sheet if necessary): Stains and discolouration.

12. Threats to the Property



SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

COMMENTS

14. Photographs Photo Reference CAPTION	(attach list as in page 6, in case of multiple photographs)
15. Audio / Video	(related to rituals / performance / festivals etc.)
Reference DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME

COMMENTS