



INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

11, Mansingh Road, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological and Heritage Sites / Monuments

Serial No.: RJ/DP-033

SECTION I: IDENTIFICATION

1. Name

Present : Gateway
 Past :
 Other Name (if any): : Shri Radh Bihari Ji Mandir

2. Location

LONGITUDE 74°23'E

LATITUDE 24°01'N

Address

Near Nath Jee Ka Mandir, Gaibsagar

: **Village (village code)**

Post: Dungarpur

District: Dungarpur

State: Rajasthan

PIN: 314301

Approach

: The Gateway is situated at Gaibsagar in Dungarpur district. It is 1km away from bus stand, Dungarpur. It is well connected by regular bus services.

3. Property Type

Buildings

- Palace
- Fort
- Citadel
- Govt. building
- Railway station
- Defence building
- Industrial building
- Other public buildings
- Residential building

Religious structures

- Temple
- Mosque
- Minar
- Church
- Monastery
- Stupa
- Tomb, Mausoleum

Other Structures

- Wall
- Gateway
- Pillar
- Others (specify)-

Engineering structure

- Bridge
- Tunnel
- Other engineering structure

Open space and related structures

- Public square
- Park or garden
- Graveyard
- Baolis, Well
- Tank
- Cave

Note: It is a gateway to the temple having multi-foliated arch opening. The arch is adorned with decorative pattern. The structure rest on circular pillars.

4. Property Use**ABANDONED / IN USE :** In use

Present : Gateway
Past : Gateway

5. Age (Source)

PERIOD : 19th Century AD
YEARS :

Precise date of Construction :
Completion :
Subsequent changes :
Destruction / Demolition :

6. Ownership / Level of Protection**SINGLE /MULTIPLE :**

Public : Archaeological Survey of India / State Archaeology Department / Any Other (Please specify)
Private :
Any other (Please specify) :
Name :
Address :
Phone :

7. Association

- **WITH EVENTS**
 - In History** :
 - In Rituals** :
 - In Building Construction** :
 - Any other (specify)** :
- **WITH PERSONS**
 - Patron** :
 - Architect / Engineer** :
 - Any other (specify)** :

8. Statement of Significance

- | | |
|-------------------------------------|---------------------------------------|
| <input checked="" type="checkbox"/> | Architectural- Multiple arch opening. |
| <input type="checkbox"/> | Archaeological |
| <input type="checkbox"/> | Historical |
| <input type="checkbox"/> | Religious |
| <input type="checkbox"/> | Any other (specify) |

:

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features

- **Context**
Urban ✓/ Rural Setting
Surroundings
*** Drawings (Attach extra sheet if necessary)**
Urban setting
Stand in Isolation
Integral part of a Landscape / Street / Complex

- **Quantification**
Area Dimension (L x B x H) : (m / cm/ feet / inch)
Number of Blocks :01
Number of Storys :01

- **Spatial Organization**
Orientation : The Gateway is oriented East/West and faces the East.
Plan :
Allocation of Spaces :

ARCHITECTURAL STYLE

- **Ornamentation**
Exteriors : Carved and decorative pattern on the arches.
Interiors :
Movable Collections : No.
Any Other (specify) :

10. Construction Technology

- | | |
|---------------------------------|-----------------|
| Structural System | Indo-Islamic. |
| Building Techniques | Arcuate system. |
| Material of Construction | Stone. |

11. Condition Assessment

In General

Good ✓/ Fair

- Sign of Deterioration
- Serious Deterioration
- Danger of Disappearance

In Brief (Attach extra sheet if necessary):

Broken staircases and fading of colour.

12. Threats to the Property

- Natural
- Negligence
- Vandalism
- Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs

(attach list as in page 6, in case of multiple photographs)

Photo Reference

CAPTION

15. Audio / Video

(related to rituals / performance / festivals etc.)

Reference

DESCRIPTION

16. Maps/Plans/Drawings

17. Listers

NAME

NAME

18. Reviewers

NAME

NAME

COMMENTS

COMMENTS