

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/DP-043

SECTION I : IDENTIFICATION

1. Name

Present : Gamleshawar Mahadev Talab
Past :
Other Name (if any): :

2. Location

LONGITUDE 74° 23'E

LATITUDE 24° 01' N

Address

Gamleshawar Mahadev Temple ,Sagwara

: **Village (village code)**
Post: Sagwara **District:** Dungarpur
State: Rajasthan **PIN:** 314025

Approach district

: The Talab is situated at Sagwara in Dungarpur district. It is 45km away from Duganpur bus stand. It is well connected by regular services.

3. Property Type

Buildings

- | | |
|--------------------------|------------------------|
| <input type="checkbox"/> | Palace |
| <input type="checkbox"/> | Fort |
| <input type="checkbox"/> | Citadel |
| <input type="checkbox"/> | Govt. building |
| <input type="checkbox"/> | Railway station |
| <input type="checkbox"/> | Defence building |
| <input type="checkbox"/> | Industrial building |
| <input type="checkbox"/> | Other public buildings |
| <input type="checkbox"/> | Residential building |

Religious structures

- | | |
|--------------------------|-----------------|
| <input type="checkbox"/> | Temple |
| <input type="checkbox"/> | Mosque |
| <input type="checkbox"/> | Minar |
| <input type="checkbox"/> | Church |
| <input type="checkbox"/> | Monastery |
| <input type="checkbox"/> | Stupa |
| <input type="checkbox"/> | Tomb, Mausoleum |

Other Structures

- | | |
|-------------------------------------|------------------|
| <input type="checkbox"/> | Wall |
| <input type="checkbox"/> | Gateway |
| <input type="checkbox"/> | Pillar |
| <input checked="" type="checkbox"/> | Others (specify) |

Talab

Engineering structure

- | | |
|--------------------------|-----------------------------|
| <input type="checkbox"/> | Bridge |
| <input type="checkbox"/> | Tunnel |
| <input type="checkbox"/> | Other engineering structure |

Open space and related structures

- | | |
|--------------------------|----------------|
| <input type="checkbox"/> | Public square |
| <input type="checkbox"/> | Park or garden |
| <input type="checkbox"/> | Graveyard |
| <input type="checkbox"/> | Baolis, Well |
| <input type="checkbox"/> | Tank |

Note: It is a pond presenting a beautiful landscape. The pond is not being maintained properly. Its water is contaminated and using for bathing and irrigation purposes.

Cave

4. Property Use

ABANDONED / IN USE ✓

Present :
Past :

5. Age (Source)

PERIOD : 14th Century AD
YEARS :
Precise date of Construction :
Completion :
Subsequent changes :
Destruction / Demolition :

6. Ownership / Level of Protection

SINGLE / MULTIPLE :

Public : Archaeological Survey of :
India / State Archaeology :
Department / Any Other (Please :
specify)state Govt. :
Private :
Any other (Please specify) :
Name :
Address :
Phone :

7. Association

•1 WITH EVENTS

In History :
In Rituals :
In Building Construction :
Any other (specify) :

•2 WITH PERSONS

Patron :
Architect / Engineer :
Any other (specify) :

8. Statement of Significance

Architectural
 Archaeological

- Historical
- Religious
- Any other (specify) _____ :

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features _____

●3 Context * Drawings (Attach extra sheet if necessary)

Urban / Rural Setting
Surroundings

Stand in Isolation Integral part of a Landscape /
Street / Complex

●4 Quantification

Area Dimension (L x B x H) : _____
(m / cm/ feet / inch)

Number of Blocks : 01

Number of Storys :

●5 Spatial Organization

Orientation : The Talab is oriented East/West and faces the West.

Plan :

Allocation of Spaces :

ARCHITECTURAL STYLE

●6 Ornamentation

Exteriors :

Interiors :

Movable Collections :

Any Other (specify) :

10. Construction Technology

Structural System : Pond having a scenic landscape.

Building Techniques :

Material of Construction :

11. Condition Assessment

In General

Good ✓/ Fair

- | | |
|--------------------------|-------------------------|
| <input type="checkbox"/> | Sign of Deterioration |
| <input type="checkbox"/> | Serious Deterioration |
| <input type="checkbox"/> | Danger of Disappearance |

In Brief (Attach extra sheet if necessary): Not well -maintained.

12. Threats to the Property

- | | |
|-------------------------------------|-----------------|
| <input checked="" type="checkbox"/> | Natural |
| <input checked="" type="checkbox"/> | Negligence |
| <input type="checkbox"/> | Vandalism |
| <input type="checkbox"/> | Urban Pressures |

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs

(attach list as in page 6, in case of multiple photographs)

**Photo Reference
CAPTION**

15. Audio / Video

(related to rituals / performance / festivals etc.)

**Reference
DESCRIPTION**

16. Maps/Plans/Drawings

17. Listers

NAME

NAME

18. Reviewers

**NAME
COMMENTS**

**NAME
COMMENTS**