

# **INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS**

Janpath, New Delhi -110 001, www.ignca.gov.in

# Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.:RJ/DP-046

| 1. Name   | SECTION I: IDENTIFICATION  |
|---|--|
| Present Past Other Name (if any): 2. Location   | : Shai Vishnu Mandir<br>:<br>:   |
| LONGITUDE 74°23'E  Address  | LATITUDE 24°01'N   |
| Approach district   | <ul> <li>Village (village code)</li> <li>Post: Dungarpur District: Dungarpur State: Rajasthan PIN: 314301</li> <li>The Temple is situated near Nathjee Mandir in Dungarpur district. It is 2km away from Dungarpur bus stand. It is well connected by regular bus services.</li> </ul> |
| 3. Property Type  |  |
| Palace Fort Citadel Govt. building Railway station Defence building Industrial building Other public buildings Residential building | Religious structures  Temple  Mosque  Minar  Church  Monastery  Stupa  Tomb, Mausoleum  Other Structures  Wall  Gateway  Pillar  Others (specify)  |
| Engineering structure  Bridge Tunnel Other engineering structure  | Open space and related<br>structuresNote:It is a Nagara style of<br>temple having Shikhara. The<br>image of 'Vishnu' and 'Shesh-nag'<br>is placed inside the 'Garbha-<br>griha'. Walls are adorned with<br>marble tiles.Tank<br>   |

| 4. Property Use  |                                    |
|--|------------------------------------|
| 4. 1 Topolty 030   | ABANDONED /IN USE √                |
| Present<br>Past  | : Religious<br>: Religious         |
| 5. Age (Source)  |                                    |
| PERIOD<br>YEARS  | : 16 <sup>th</sup> Century AD<br>: |
| Precise date of Construction<br>Completion<br>Subsequent changes   | :<br>:<br>:                        |
| Destruction / Demolition   | :                                  |
| 6. Ownership / Level of Protection   | ion                                |
|  | SINGLE /MULTIPLE :                 |
| Public: Archaeological Survey of India / State Archaeology Department / Any Other (Please specify)state Govt. Private Any other (Please specify) | :<br>:                             |
| Name   | :                                  |
| Address  | :                                  |
| Phone  | :                                  |
| 7. Association   |                                    |
| WITH EVENTS  |                                    |
| In History<br>In Rituals   | :                                  |
| In Building Construction   | . :                                |
| Any other (specify)  • WITH PERSONS  | :                                  |
| Patron   | :                                  |
| Architect / Engineer   | :                                  |
| Any other (specify)  | :                                  |
| 8. Statement of Significance   |                                    |
| <ul><li>✓ Architectural</li><li>✓ Archaeological</li><li>Historical</li><li>Religious</li></ul>  | 'Shikhara' crowned by an 'Amalaka' |

| Any other (specify) : |  |
|-----------------------|--|
|-----------------------|--|

#### **SECTION II: DESCRIPTION**

### 9. Physical Description and Decorative Features

Context

Urban √ Rural Setting Surroundings

\* **Drawings (**Attach extra sheet if necessary)

Stand in Isolation

Integral part of a Landscape / Street / Complex

Quantification

Area Dimension ( $L \times B \times H$ ):

(m / cm/ feet / inch)

Number of Blocks 01 01 Number of Storys

**Spatial Organization** 

Orientation The Temple is oriented North/South and faces the

South. .

Plan

Allocation of Spaces

**ARCHITECTURAL STYLE** 

Ornamentation

Exteriors Black color image of Lord 'Vishnu' and 'Shesh- naga'

having lustrous gloss.

Interiors

**Movable Collections** 

Ritualistic objects.

Any Other (specify)

10. Construction Technology

Structural System Nagara style of temple.

**Building Techniques** Trabeate system **Material of Construction** Stone and plaster.

| 11. Condition Assessment   |   |  |
|--|---|--|
| In General   | Good√ / Fair  |  |
|  | Sign of Deterioration Serious Deterioration Danger of Disappearance |  |
| In Brief (Attach extra sheet if necessary): Peeling of plaster, broken chhajjas, discolouration, |   |  |
| bad electric fittings etc.   |   |  |
| 12. Threats to the Property  |   |  |
| 12. Tilledis to the Froperty   |   |  |
|  | _√_ Natural   |  |
|  | Negligence  |  |
|  | √ Vandalism   |  |
|  | Urban Pressures   |  |

# SECTION III: REFERENCES

### 13. Reference Sources (published and unpublished textual details)

| 14. Photographs         |   |
|-------------------------|---|
|                         | (attach list as in page 6, in case of multiple photographs) |
| Photo Reference         |   |
| CARTION                 |   |
| CAPTION                 |   |
| 15. Audio / Video       |   |
|                         | (related to rituals / performance / festivals etc.)         |
| Reference               |   |
| DESCRIPTION             |   |
| 40.14 (D) (D)           |   |
| 16. Maps/Plans/Drawings |   |
|                         |   |
|                         |   |
| 17. Listers             |   |
| NA BAT                  | MARAC   |
| NAME                    | NAME  |
| 18. Reviewers           |   |
| NAME                    | NAME  |
|                         |   |
| COMMENTS                | COMMENTS  |