



# INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

11, Mansingh Road, New Delhi -110 001, [www.ignca.gov.in](http://www.ignca.gov.in)

## Documentation format for Archaeological and Heritage Sites / Monuments

Serial No.: RJ/DP-052

### SECTION I: IDENTIFICATION

#### 1. Name

**Present** : Ek Linginath Jee ka Mandir  
**Past** :  
**Other Name (if any):** :

#### 2. Location

**LONGITUDE** 74°23'E

**LATITUDE** 24°01'N

#### Address

Shree Radha Bihari Jee Ka Mandir, Gaibsagar

: **Village (village code)**

**Post:** Dungarpur

**District:** Dungarpur

**State:** Rajasthan

**PIN:** 314301

#### Approach

: The Temple is situated at Gaibsagar in Dungarpur district. It is 45km away from Dungarpur bus stand. It is well connected by regular bus services.

#### 3. Property Type

##### **Buildings**

- Palace
- Fort
- Citadel
- Govt. building
- Railway station
- Defence building
- Industrial building
- Other public buildings
- Residential building

##### **Religious structures**

- Temple
- Mosque
- Minar
- Church
- Monastery
- Stupa
- Tomb, Mausoleum

##### **Other Structures**

- Wall
- Gateway
- Pillar
- Others (specify)

##### **Engineering structure**

- Bridge
- Tunnel
- Other engineering structure

##### **Open space and related structures**

- Public square
- Park or garden
- Graveyard
- Baolis, Well
- Tank
- Cave

**Note:** This is a temple dedicated to lord Shiva. It is built in Nagara style. The Shikhara of the temple is crowned by double 'Amalaka' parapet having petalled designs.

---

**4. Property Use****ABANDONED / IN USE :**

**Present** : Religious  
**Past** : Religious

---

**5. Age (Source)**

**PERIOD** : 19<sup>th</sup> Century AD  
**YEARS** :

**Precise date of Construction** :  
**Completion** :  
**Subsequent changes** :  
**Destruction / Demolition** :

---

**6. Ownership / Level of Protection****SINGLE /MULTIPLE :**

**Public** : Archaeological Survey of India / State Archaeology Department / Any Other (Please specify)  
**Private** :  
**Any other (Please specify)** :  
**Name** :  
**Address** :  
**Phone** :

---

**7. Association**

- **WITH EVENTS**
  - In History** :
  - In Rituals** :
  - In Building Construction** :
  - Any other (specify)** :
- **WITH PERSONS**
  - Patron** :
  - Architect / Engineer** :
  - Any other (specify)** :

---

**8. Statement of Significance**

|                                     |                                                       |   |
|-------------------------------------|-------------------------------------------------------|---|
| <input checked="" type="checkbox"/> | Architectural- Shikhara crowned by double 'Amalakas'. |   |
| <input type="checkbox"/>            | Archaeological                                        |   |
| <input type="checkbox"/>            | Historical                                            |   |
| <input type="checkbox"/>            | Religious                                             |   |
| <input type="checkbox"/>            | Any other (specify)                                   | : |

## SECTION II: DESCRIPTION

### 9. Physical Description and Decorative Features

---

- **Context**  
**Urban√ / Rural Setting**  
**Surroundings**  
**\* Drawings (Attach extra sheet if necessary)**  
Urban setting  
  
**Stand in Isolation**  
**Integral part of a Landscape / Street / Complex**
  
- **Quantification**  
Area Dimension ( L x B x H) :  
(m / cm/ feet / inch)  
  
Number of Blocks : 01  
Number of Storys : 01
  
- **Spatial Organization**  
Orientation : The Temple is oriented East/West and faces the East.  
Plan :  
Allocation of Spaces :

### ARCHITECTURAL STYLE

- **Ornamentation**  
Exteriors : Parapet having petalled designs.  
Interiors : Black stone image of Nandi.  
Movable Collections :  
**Any Other (specify)** :

### 10. Construction Technology

---

|                                 |                        |
|---------------------------------|------------------------|
| <b>Structural System</b>        | Nagara style of temple |
| <b>Building Techniques</b>      | Trabeate system        |
| <b>Material of Construction</b> | Stone                  |

## 11. Condition Assessment

---

**In General**

**Good√ / Fair**

- |                          |                         |
|--------------------------|-------------------------|
| <input type="checkbox"/> | Sign of Deterioration   |
| <input type="checkbox"/> | Serious Deterioration   |
| <input type="checkbox"/> | Danger of Disappearance |

### **In Brief (Attach extra sheet if necessary):**

Flooring is in bad condition. Cracks and discoloration can be seen.

---

## 12. Threats to the Property

- |                                     |                 |
|-------------------------------------|-----------------|
| <input checked="" type="checkbox"/> | Natural         |
| <input type="checkbox"/>            | Negligence      |
| <input type="checkbox"/>            | Vandalism       |
| <input type="checkbox"/>            | Urban Pressures |

### **SECTION III: REFERENCES**

#### **13. Reference Sources** (published and unpublished textual details)

---

#### **14. Photographs**

(attach list as in page 6, in case of multiple photographs)

##### **Photo Reference**

##### **CAPTION**

#### **15. Audio / Video**

(related to rituals / performance / festivals etc.)

##### **Reference**

##### **DESCRIPTION**

#### **16. Maps/Plans/Drawings**

---

#### **17. Listers**

---

##### **NAME**

##### **NAME**

#### **18. Reviewers**

---

##### **NAME**

##### **NAME**

##### **COMMENTS**

##### **COMMENTS**