

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.:RJ/Dp-066

1. Name	SECTION I: IDENTIFICATION	
Present Past Other Name (if any): 2. Location	: Durga Mata Mandir : :	
LONGITUDE 74°23'E	LATITUDE 24°01'N	
Address	In Front of Nagar, Palika Du	ngarpur
	: Village (village code)	
Approach district		District: Dungarpur PIN: 314001 at Dungarpur. It is 2km away parpur. It is well connected by
3. Property Type		
Palace Fort Citadel Govt. building Railway station Defence building Industrial building Other public building Residential building	Religious structures Temple Mosque Minar Church Monastery Stupa Tomb, Mausoleum	Other Structures Wall Gateway Pillar Others (specify)
Engineering structure Bridge Tunnel Other engineering structure	structures N Public square S Park or garden	lote: It is a small temple of lagara style. It has curvilinear hihar with angashikhar. The Garbha griha'has image of dirty vith lustrous gloss.

4. Property Use	
	ABANDONED /IN USE √
Present Past	: Religious: Religious
5. Age (Source)	
PERIOD YEARS	: 16 th Century AD :
Precise date of Construction Completion Subsequent changes Destruction / Demolition	: : :
6. Ownership / Level of Protection	ion
	SINGLE /MULTIPLE :
India / State Archaeology Department / Any Other (Please specify)state Govt. Private	:
Any other (Please specify)	:
Name Address	:
Phone	:
Thomas and the second s	•
7. Association	
WITH EVENTS	
In History	:
In Rituals	:
In Building Construction	
Any other (specify) • WITH PERSONS	•
Patron	:
Architect / Engineer	:
Any other (specify)	:
8. Statement of Significance	
✓ Architectural✓ ArchaeologicalHistoricalReligious	Shikhara crowned by an'Amalaka'

Any other (specify)	:	
	SECTION II: DESCRIPTION	

9. Physical Description and Decorative Features

Context

Urban √/ Rural Setting Surroundings

* **Drawings** (Attach extra sheet if necessary)

Stand in Isolation

Integral part of a Landscape / Street / Complex

Quantification

Area Dimension (LxBxH):

(m / cm/ feet / inch)

Number of Blocks : 01 Number of Storys : 01

• Spatial Organization

Orientation : The Temple is oriented North/South and faces the

North.

Plan :

Allocation of Spaces

ARCHITECTURAL STYLE

Ornamentation

Exteriors : Image of dirty with lustrous gloss.

Interiors : Ritualistic objects.

Movable Collections

Any Other (specify) :

10. Construction Technology

Structural System : Nagara style of temple. **Building Techniques** : Trabeate system.

Material of Construction : Stone.

11. Condition Assessment	
In General	Good√ / Fair
	Sign of Deterioration Serious Deterioration Danger of Disappearance
In Brief (Attach extra sheet i	f necessary): Peeling of plaster, accumulation of dust and dirt.
12. Threats to the Property	
	Natural √ Negligence Vandalism Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
0.177.01	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS