INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.:RJ/DP-100

1. Name	SECTION I: IDENTIFICATION	N
Present Past Other Name (if any):	: Udaivilash : :	
2. Location		
LONGITUDE 74°23'E	LATITUDE 24°01'N	
Address	Udaivilas, Dungarpur : Village (village code) Post: Dungarpur	District : Dungarpur
Approach district		PIN: 314001 If at Dungarpur. It is 2km away pur. It is well connected by
3. Property Type		
Buildings Palace Fort Citadel Govt. building Railway station Defence building Industrial building Other public building Residential building	Religious structures Temple Mosque Minar Church Monastery Stupa Tomb, Mausoleum	Other Structures Wall Gateway Pillar √ Others (specify) Mahal
Engineering structure	Open space and related structures	Note: It is a beautiful palacial building having projected balconies supported by stone brackets. It is a triple storied Masonic structure. The entrance to the Maher is through a gate having foliated arch opening. The projected balconies are adorned with colorful foliated arch opening.
Bridge Tunnel	Public square Park or garden	

Other engineering structure	Graveyard
	Baolis, Well
	Tank
	Cave

4. Property Use

ABANDONED / IN USE

Present : Residential Past : Residential

5. Age (Source)

PERIOD : 16th Century AD

YEARS

Precise date of Construction : Completion : Subsequent changes : Destruction / Demolition :

6. Ownership / Level of Protection

SINGLE /MULTIPLE:

Public: Archaeological Survey of : India / State Archaeology

Department / Any Other (Please

specify)state Govt.

Private : Any other (Please specify) : Name : Address : Phone :

7. Association

•1 WITH EVENTS

In History : In Rituals : In Building Construction : Any other (specify) :

•2 WITH PERSONS

Patron :
Architect / Engineer :
Any other (specify) :

8. Statement of Significance

 √ Architectural Archaeological Historical Religious Any other (specify) 	Pı :	rojected Balconies
<u>s</u>	SEC	TION II: DESCRIPTION
9. Physical Description and Dec	cora	tive Features
•3 Context Urban √/ Rural Setting Surroundings		* Drawings (Attach extra sheet if necessary) Stand in Isolation Integral part of a Landscape /
		Street / Complex
•4 Quantification Area Dimension (LxBxH) Number of Blocks Number of Storys	: : : :	(m / cm/ feet / inch)
 5 Spatial Organization Orientation Plan Allocation of Spaces 	: :	The Building is oriented East/West and faces the Wast
•6 Ornamentation Exteriors Interiors Movable Collections Any Other (specify)	: : : : : : : : : : : : : : : : : : : :	
10. Construction Technology		
Structural System Building Techniques Material of Construction	: : :	

11. Condition Assessment	
In General	Good√ / Fair
	Sign of Deterioration Serious Deterioration Danger of Disappearance
In Brief (Attach extra sheet	if necessary): well maintained with its historicity.
Blackening of the surface	
12. Threats to the Property	
	√ Natural
	Negligence Vandalism
	Urban Pressures

SECTION III: REFERENCES

Reference Sources (published and unpublished textual deta

14. Photographs(attach list as in page 6, in case of multiple photographs)

Photo Reference CAPTION

15. Audio / Video (related to rituals / performance / festivals etc.)

Reference DESCRIPTION

16. Maps/Plans/Drawings

17. Listers

NAME NAME

18. Reviewers

NAME NAME

COMMENTS COMMENTS