

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

SerialNo.:RJ/DP-107

SECTION I : IDENTIFICATION

1. Name

Present : Ganesh Jee Ka Mandir
Past :
Other Name (if any): :

2. Location

LONGITUDE 74°23'E **LATITUDE** 24°01'N

Address Near Udaivilash Dungarpur

: **Village (village code)**
Post: Dungarpur **District:** Dungarpur
State: Rajasthan **PIN:** 314001

Approach district: - The Temple is situated at Dungarpur district. It is 12km away from Dungarpur bus stand. It is well connected by regular bus services.

3. Property Type

Buildings

- | | |
|--------------------------|------------------------|
| <input type="checkbox"/> | Palace |
| <input type="checkbox"/> | Fort |
| <input type="checkbox"/> | Citadel |
| <input type="checkbox"/> | Govt. building |
| <input type="checkbox"/> | Railway station |
| <input type="checkbox"/> | Defence building |
| <input type="checkbox"/> | Industrial building |
| <input type="checkbox"/> | Other public buildings |
| <input type="checkbox"/> | Residential building |

Engineering structure

- | | |
|--------------------------|--------|
| <input type="checkbox"/> | Bridge |
| <input type="checkbox"/> | Tunnel |

Religious structures

- | | |
|-------------------------------------|-----------------|
| <input checked="" type="checkbox"/> | Temple |
| <input type="checkbox"/> | Mosque |
| <input type="checkbox"/> | Minar |
| <input type="checkbox"/> | Church |
| <input type="checkbox"/> | Monastery |
| <input type="checkbox"/> | Stupa |
| <input type="checkbox"/> | Tomb, Mausoleum |

Open space and related structures

- | | |
|--------------------------|----------------|
| <input type="checkbox"/> | Public square |
| <input type="checkbox"/> | Park or garden |

Other Structures

- | | |
|--------------------------|------------------|
| <input type="checkbox"/> | Wall |
| <input type="checkbox"/> | Gateway |
| <input type="checkbox"/> | Pillar |
| <input type="checkbox"/> | Others (specify) |

Note: It is a small temple having decorative parapet. The temple is clad with lime-plaster. It has a bulbous dome surmounted by an inverted lotus type of Pinnaels. 'Garbha-griha' has a beautiful image of the deity in traditional attire.

- | | | | |
|--------------------------|-----------------------------|--------------------------|--------------|
| <input type="checkbox"/> | Other engineering structure | <input type="checkbox"/> | Graveyard |
| | | <input type="checkbox"/> | Baolis, Well |
| | | <input type="checkbox"/> | Tank |
| | | <input type="checkbox"/> | Cave |

4. Property Use

ABANDONED / IN USE ✓

Present : Religious
Past : Religious

5. Age (Source)

PERIOD : 18th Century AD
YEARS :
Precise date of Construction :
Completion :
Subsequent changes :
Destruction / Demolition :

6. Ownership / Level of Protection

SINGLE / MULTIPLE :

Public : Archaeological Survey of India / State Archaeology Department / Any Other (Please specify)state Govt. :
Private :
Any other (Please specify) :
Name :
Address :
Phone :

7. Association

•1 **WITH EVENTS**
In History :
In Rituals :
In Building Construction :
Any other (specify) :
•2 **WITH PERSONS**
Patron :
Architect / Engineer :
Any other (specify) :

8. Statement of Significance

<input checked="" type="checkbox"/>	Architectural	Dome surmounted by inverted lotus type of pinnae.
<input type="checkbox"/>	Archaeological	
<input type="checkbox"/>	Historical	
<input type="checkbox"/>	Religious	
<input type="checkbox"/>	Any other (specify)	:

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features _____

●3 Context * Drawings (Attach extra sheet if necessary)

Urban Rural Setting
Surroundings

**Stand in Isolation Integral part of a Landscape /
Street / Complex**

●4 Quantification

Area Dimension (L x B x H) :
(m / cm/ feet / inch)
Number of Blocks : 01
Number of Storys : 01

●5 Spatial Organization

Orientation : The Temple is oriented North/South and faces the North.
Plan :
Allocation of Spaces :

ARCHITECTURAL STYLE

●6 Ornamentation

Exteriors : cladded with lime-plaster, dome having inverted lotus type of pinnae.
Interiors : Image of dirty with traditional attire.
Movable Collections : Rihealistic objects.
Any Other (specify) :

10. Construction Technology

Structural System : Indo-Islamic
Building Techniques : Arcuate system
Material of Construction : Stone and plaster.

11. Condition Assessment

In General

Good√ / Fair

- | | |
|--------------------------|-------------------------|
| <input type="checkbox"/> | Sign of Deterioration |
| <input type="checkbox"/> | Serious Deterioration |
| <input type="checkbox"/> | Danger of Disappearance |

In Brief (Attach extra sheet if necessary): Peeling of plaster, discolouration etc.

12. Threats to the Property

- | | |
|-------------------------------------|-----------------|
| <input checked="" type="checkbox"/> | Natural |
| <input type="checkbox"/> | Negligence |
| <input type="checkbox"/> | Vandalism |
| <input type="checkbox"/> | Urban Pressures |

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs

(attach list as in page 6, in case of multiple photographs)

**Photo Reference
CAPTION**

15. Audio / Video

(related to rituals / performance / festivals etc.)

**Reference
DESCRIPTION**

16. Maps/Plans/Drawings

17. Listers

NAME

NAME

18. Reviewers

**NAME
COMMENTS**

**NAME
COMMENTS**