



INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/JWR-121

SECTION I : IDENTIFICATION

1. Name

Present : Nasia jee ki Baoli
Past :
Other Name (if any): :

2. Location

LONGITUDE 76° 56' E

LATITUDE 24° 52' N

Address

Near-Sigma School, Jhalara Patan, Jalawara

: **Village (village code)**

Post : Jhalara Patan

District: Jalawara

State : Rajasthan

PIN: 326023

Approach

:

3. Property Type

Buildings

- | | |
|--------------------------|------------------------|
| <input type="checkbox"/> | Palace |
| <input type="checkbox"/> | Fort |
| <input type="checkbox"/> | Citadel |
| <input type="checkbox"/> | Govt. building |
| <input type="checkbox"/> | Railway station |
| <input type="checkbox"/> | Defence building |
| <input type="checkbox"/> | Industrial building |
| <input type="checkbox"/> | Other public buildings |
| <input type="checkbox"/> | Residential building |

Religious structures

- | | |
|--------------------------|-----------------|
| <input type="checkbox"/> | Temple |
| <input type="checkbox"/> | Mosque |
| <input type="checkbox"/> | Minar |
| <input type="checkbox"/> | Church |
| <input type="checkbox"/> | Monastery |
| <input type="checkbox"/> | Stupa |
| <input type="checkbox"/> | Tomb, Mausoleum |

Other Structures

- | | |
|--------------------------|------------------|
| <input type="checkbox"/> | Wall |
| <input type="checkbox"/> | Gateway |
| <input type="checkbox"/> | Pillar |
| <input type="checkbox"/> | Others (specify) |

Engineering structure

- | | |
|--------------------------|-----------------------------|
| <input type="checkbox"/> | Bridge |
| <input type="checkbox"/> | Tunnel |
| <input type="checkbox"/> | Other engineering structure |

Open space and related structures

- | | |
|--------------------------|----------------|
| <input type="checkbox"/> | Public square |
| <input type="checkbox"/> | Park or garden |
| <input type="checkbox"/> | Graveyard |
| <input type="checkbox"/> | Baolis, Well |
| <input type="checkbox"/> | Tank |
| <input type="checkbox"/> | Cave |

Note: This is a water reservoir named as Nasia jee ki Baoli. It has well managed staircases. It has pillars with capital giving support to upper structure. Chajja of it is supported by bracket.

4. Property Use

ABANDONED / IN USE : In use

Present :
Past :

5. Age (Source)

PERIOD : 17th Century A.D.
YEARS :
Precise date of Construction :
Completion :
Subsequent changes :
Destruction / Demolition :

6. Ownership / Level of Protection

SINGLE /MULTIPLE :

Public : Archaeological Survey of :
India / State Archaeology
Department / Any Other (Please
specify)
Private :
Any other (Please specify) :
Name :
Address :
Phone :

7. Association

- **WITH EVENTS**
 - In History** :
 - In Rituals** :
 - In Building Construction** :
 - Any other (specify)** : Water reservoir
- **WITH PERSONS**
 - Patron** :
 - Architect / Engineer** :
 - Any other (specify)** :

8. Statement of Significance

<input type="checkbox"/>	Architectural	Staircases
<input type="checkbox"/>	Archaeological	
<input type="checkbox"/>	Historical	
<input type="checkbox"/>	Religious	
<input type="checkbox"/>	Any other (specify)	

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features

- **Context**
Urban / Rural Setting
Surroundings
*** Drawings** (Attach extra sheet if necessary)
Urban

Stand in Isolation
Integral part of a Landscape / Street / Complex
- **Quantification**
Area Dimension (L x B x H) :

Number of Blocks : 01
Number of Storys : 02

(m / cm/ feet / inch)
- **Spatial Organization**
Orientation : The Boali is oriented East-West and faces the West
Plan :
Allocation of Spaces :

ARCHITECTURAL STYLE

- **Ornamentation**
Exteriors : Staircases
Interiors :
Movable Collections :
Any Other (specify) :

10. Construction Technology

Structural System : Indo-Persian
Building Techniques : Arcuate system
Material of Construction : Stone and plaster

11. Condition Assessment

In General **Good / Fair**
Good

- ☐ Sign of Deterioration
- ☐ Serious Deterioration
- ☐ Danger of Disappearance

In Brief (Attach extra sheet if necessary):

Algae formation, dust and dirt deposition, blackening of surface.

12. Threats to the Property

<input type="checkbox"/>	Natural
<input type="checkbox"/>	Negligence
<input type="checkbox"/>	Vandalism
<input type="checkbox"/>	Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs

(attach list as in page 6, in case of multiple photographs)

Photo Reference

CAPTION

15. Audio / Video

(related to rituals / performance / festivals etc.)

Reference

DESCRIPTION

16. Maps/Plans/Drawings

17. Listers

NAME

NAME

18. Reviewers

NAME

NAME

COMMENTS

COMMENTS