

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/JWR-344 **SECTION I: IDENTIFICATION** 1. Name Present Buddhist Mandir - 17 Past Other Name (if any): 2. Location 24⁰ 52' N LONGITUDE 76° 56' E LATITUDE **Address** Kaulvi Caves, Kaulvi, Dag Road, Jhalawar Village (village code) Kaulvi Post: Kaulvi **District:** Jhalawara State: Rajasthan PIN: 326514 Approach The temple is situated at Kaulvi in Jhalawar district. It is 90 k.m. away from Jhalawar. It is well connected by regular bus services. 3. Property Type **Buildings** Religious structures Other Structures Wall Palace Temple Fort Mosque Gateway Citadel Minar Pillar Govt. building Church Others (specify) Railway station Monastery Defence building Stupa Industrial building Tomb, Mausoleum Other public buildings Residential building Engineering structure Open space and related Note: The temple has multistructures cusped arches entrance. It has Public square made on an elevated platform with Bridge raised staircases. In the interior, it Tunnel Park or garden has image of seated Buddha. Other engineering structure Graveyard Baolis, Well Tank

Cave

4. Property Use	
	ABANDONED / IN USE: Abandoned
Present Past	: Religious
5. Age (Source)	
PERIOD YEARS Precise date of Construction Completion Subsequent changes Destruction / Demolition	: 6 th Century A.D. : : :
6. Ownership / Level of Protection	SINGLE /MULTIPLE :
Public: Archaeological Survey of India / State Archaeology Department / Any Other (Please specify) Private	
Any other (Please specify) Name Address Phone	: : : :
7. Association	
 WITH EVENTS In History In Rituals In Building Construction Any other (specify) WITH PERSONS Patron Architect / Engineer Any other (specify) 	Buddhist Temple:::::::
8. Statement of Significance	
 ✓ Architectural ✓ Archaeological Historical Religious Any other (specify) 	The temple has multi-cusped arch entrance

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features					
Context Urban / Rural Setting Surroundings			* Drawings (Attach extra sheet if necessary) Rural		
			Stand in Isolation Integral part of a Landscape / Street / Complex		
	Quantification Area Dimension(L x B x H	H) :	(m / cm/ feet / inch)		
	Number of Blocks Number of Storys	:	01 01		
	Spatial Organization Orientation Plan Allocation of Spaces	: :	The Temple is oriented East-West and faces the East		
•	CHITECTURAL STYLE Ornamentation Exteriors Interiors Movable Collections Other (specify)	: : :	Multi-cusped arches Buddha		
10.	Construction Technology	у			
	Structural System Building Techniques Material of Construction	: : :	Chaitya Rock-cut caves (man-made cave) Stone		
11.	Condition Assessment				
	In General	Good Good	/ Fair		
	Sign of Deterioration Serious Deterioration Danger of Disappearance)			
In B	Brief (Attach extra sheet i	f neces	ssary):		
ام/۸/	I maintained				

12. Threats to the Property	
	Natural Negligence Vandalism Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS