

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/JWR-352 **SECTION I: IDENTIFICATION** 1. Name Present Buddhist Mandir - 47 Past Other Name (if any): 2. Location 24⁰ 52' N LONGITUDE 76° 56' E LATITUDE **Address** Kaulvi Caves, Kaulvi, Dag Road, Jhalawar Village (village code) Kaulvi Post: Kaulvi **District:** Jhalawara State: Rajasthan PIN: 326514 **Approach** The Temple is situated at Kaulvi in Jhalawar district. It is 90 k.m. away from Jhalawar. It is well connected by regular bus services. 3. Property Type **Buildings** Religious structures Other Structures Wall Palace Temple Fort Mosque Gateway Citadel Minar Pillar Govt. building Church Others (specify) Railway station Monastery Defence building Stupa Industrial building Tomb, Mausoleum Other public buildings Residential building Engineering structure Open space and related Note: The Buddhist temple is made on an elevated platform. It structures Public square has a chhajja and the temple has Bridge many windows. It has staircases. Park or garden Tunnel They are man-made is the surface Graveyard Other engineering structure is rough. Baolis, Well Tank

Cave

4. Property Use	
	ABANDONED / IN USE: Abandoned
Present Past	: Religious
5. Age (Source)	
PERIOD YEARS Precise date of Construction Completion Subsequent changes Destruction / Demolition	: 6 th Century A.D. : :
6. Ownership / Level of Protection	
Public: Archaeological Survey of India / State Archaeology Department / Any Other (Please specify) Private Any other (Please specify) Name Address Phone 7. Association	SINGLE /MULTIPLE : : : : : : : : : : : : : : : : : : :
 WITH EVENTS In History In Rituals In Building Construction Any other (specify) WITH PERSONS Patron Architect / Engineer Any other (specify) Statement of Significance 	Buddhisht templeBuddhisht tem
✓ Architectural Archaeological Historical Religious Any other (specify)	The temple is made on an elevated platform with multiple windows.

SECTION II: DESCRIPTION

9. 1	Physical Description and	Decora	ative Features
Context Urban / Rural Setting Surroundings			* Drawings (Attach extra sheet if necessary) Rural
	Curroundings		Stand in Isolation Integral part of a Landscape / Street / Complex
•	Quantification Area Dimension (L x B x F	H) :	(m / cm/ feet / inch)
	Number of Blocks Number of Storys	:	01 01
•	Spatial Organization Orientation Plan Allocation of Spaces	: :	The Temple is oriented North-South and faces the North
•	CHITECTURAL STYLE Ornamentation Exteriors Interiors Movable Collections y Other (specify)	: : : : :	Windows, Chhajja
10.	Construction Technology	y	
	Structural System Building Techniques Material of Construction	: :	Chaitya Rock-cut temple Stone
11.	Condition Assessment		
	In General	Good / Fair	/ Fair
	Sign of Deterioration Serious Deterioration Danger of Disappearance	e	
In I	Brief (Attach extra sheet i	f neces	ssary):
Cra	acks in the structure		

12. Threats to the Property	
	Natural Negligence Vandalism Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CARTION	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
10. Maps/Flatis/Drawlings	
17. Listers	
NAME	NAME
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS