

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/KTA-054 **SECTION I: IDENTIFICATION** 1. Name Present Prachin Kund Past Other Name (if any): 2. Location 25⁰ 51['] N LONGITUDE 77° 26' E LATITUDE **Address** Char Bagh Village (village code) Post: Kota District: Kota State: Rajasthan PIN: 324006 Approach This Kund is situated in Char Bagh. It is 2 km away from Kota bus stand. It is well connected by bus services. 3. Property Type **Other Structures Buildings** Religious structures Temple Wall Palace Fort Mosque Gateway Citadel Minar Pillar Govt. building Church Others (specify) Railway station Monastery Defence building Stupa Industrial building Tomb, Mausoleum Other public buildings Residential building Engineering structure Open space and related Note: This is an ancient water structures reservoir. Near water reservoir Public square there is a structure with foliated Bridge arch opening. Tunnel Park or garden Other engineering structure Graveyard Baolis, Well

Tank Cave

4. Property Use	
	ABANDONED / IN USE :
Present Past	: Religious : Religious
5. Age (Source)	
PERIOD YEARS Precise date of Construction Completion Subsequent changes Destruction / Demolition	: 18 th Century A.D. :
6. Ownership / Level of Protecti	
Public: Archaeological Survey of India / State Archaeology Department / Any Other (Please specify) Private Any other (Please specify) Name Address Phone	SINGLE /MULTIPLE : : : : : : : : : : : :
WITH EVENTS In History In Rituals In Building Construction Any other (specify) WITH PERSONS Patron Architect / Engineer Any other (specify) Statement of Significance	: Water reservoir (Kund) : :
8. Statement of Significance Architectural Archaeological Historical Religious Any other (specify)	Water reservoir(Kund)

SECTION II: DESCRIPTION

9.	Physical Description and I	Decora	rative Features	
 Context Urban / Rural Setting Surroundings 			* Drawings (Attach extra sheet if necessary) Urban	
	Ourroundings		Stand in Isolation Integral part of a Landscape / Street / Compl	ex
•	Quantification Area Dimension (L x B x H	· i	(m. / a.m.) f	oot / in ab)
	Number of Blocks Number of Storys	: :	01 (m / cm/ fe	et / inch)
•	Spatial Organization Orientation Plan Allocation of Spaces	: : :		
<u>AF</u>	CCHITECTURAL STYLE Ornamentation Exteriors Interiors Movable Collections	: :	Foliated arch opening	
An	y Other (specify)	:		
10	. Construction Technology	/		
	Structural System Building Techniques Material of Construction	: :	Water reservoir Hydraulic system Stone and plaster	
11	. Condition Assessment			
	iii oonorai	Good Good	d / Fair I	
	Sign of Deterioration Serious Deterioration Danger of Disappearance)		
In	Brief (Attach extra sheet if	neces	essary):	
Bla	ackening of surface, plaster (peeling	ng.	

12. Threats to the Property	
	Natural Negligence Vandalism Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS