


Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/PLI - 056

1. Name	SECTION I : IDENTIFICATION
Present Past Other Name (if any): 2. Location	: Dada Jin Kushal Ji ka Smarak : :
LONGITUDE 74 ⁰ 20 ['] E	LATITUDE $26^{\circ} 75^{\circ} N$
Address	Manpura Bhakhari, Pali
	: Village (village code) Post : Pali city District: Pali State : Rajasthan PIN: 306401
Approach	: The Smarak is situated at Man Pura Bhakhari in Pali. It is 5 KM away from Pali Bus Stand. It is well connected by regular bus services.

3. Property Type



4. Property Use

	ABANDONED / IN USE : Abandoned
Present	: Memoriyal
Past	: Memoriyal
5. Age (Source)	
PERIOD YEARS	: 18 th Century A.D.
Precise date of Construction	
Completion	
Subsequent changes	:
Destruction / Demolition	:
6. Ownership / Level of Protection	on
	SINGLE /MULTIPLE :
Public : Archaeological Survey of	:
India / State Archaeology	
Department / Any Other (Please	
specify) Private	
Any other (Please specify)	
Name	
Address	
Phone	:
7. Association	
WITH EVENTS In History	
In Rituals	Living temple
In Building Construction	:
Any other (specify)	:
WITH PERSONS	
Patron	:
Architect / Engineer	:
Any other (specify)	:
8. Statement of Significance	
✓ Architectural	
Archaeological	
Historical	
Religious	
Any other (specify)	Hexagonal temple with Khaprel roof.

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features			
•	Context		* Drawings (Attach extra sheet if necessary)
Urban / Rural Setting		Rural	
	Surroundings		Stand in Isolation Integral part of a Landscape / Street / Complex
•	Quantification Area Dimension (L x B x H)	:	(m / cm/ feet / inch)
	Number of Blocks Number of Story's	:	01 01
•	Spatial Organization Orientation	:	The Smarak is oriented North - South and faces the South.
	Plan	:	
	Allocation of Spaces	:	
ARCHITECTURAL STYLE			
•	Ornamentation Exteriors	:	Khaprel roof
	Interiors Movable Collections	:	Hexanonal roof with statue

10. Construction Technology

Any Other (specify)

:

Structural System Building Techniques	:	Trabeate system
Material of Construction	:	Stone, plaster.

11. Condition Assessment

In General

Good / Fair Good

Sign of Deterioration

Serious Deterioration

Danger of Disappearance

In Brief (Attach extra sheet if necessary):

12. Threats to the Property

Natural
Negligence
Vandalism
Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(Attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(Related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS