

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

•		
Documentation format for Archaeological / Heritage Sites / Monuments		
1. Name	SECTION I: IDENTIFICATION	Serial No.: RJ/PLI - 133
Present Past Other Name (if any): 2. Location	: Chandar Prabhu Jain Ma : :	andir
LONGITUDE 74° 20' E	LATITUDE 26 ⁰ 75 ['] N	
Address	Shree Man mohan Parashav	v Nath Mandir, Bali, Pali
Approach 3. Property Type	•	District: Pali PIN: 306701 It Bali in Pali. It is 78 KM away vell connected by regular bus
3. Froperty Type		
Palace Fort Citadel Govt. building Railway station Defence building Industrial building Other public building Residential building	Religious structures Temple Mosque Minar Church Monastery Stupa Tomb, Mausoleum	Other Structures Wall Gateway Pillar Others (specify)
Engineering structure Bridge Tunnel Other engineering structure	structures m Public square a Park or garden s Graveyard w Baolis, Well w Tank h Cave fil	lote: This is a Jain temple. It is nade upon elevated platform. It is three storied building. There are culpture of elephant and lion on vall. Railing of temple has lattice vork. It has cloistered verandah. It as highly decorative ceiling with ying celestial. Sanctum anctorum enshrines Buddha.

4. Property Use	
	ABANDONED / IN USE: In use
Present Past	: Religious: Religious
5. Age (Source)	
PERIOD YEARS Precise date of Construction Completion Subsequent changes Destruction / Demolition 6. Ownership / Level of Protecti	: 17 th Century A.D. : : :
	SINGLE /MULTIPLE :
Public: Archaeological Survey of India / State Archaeology Department / Any Other (Please specify) Private Any other (Please specify) Name Address Phone	
7. Association	
 WITH EVENTS In History In Rituals In Building Construction Any other (specify) WITH PERSONS Patron Architect / Engineer Any other (specify) 	: : : : Temple :
8. Statement of Significance	
Architectural Archaeological Historical Religious Any other (specify)	Lattice pattern

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features

• Context * Drawings (Attach extra sheet if necessary)

Urban / Rural Setting

Surroundings

Rural

Stand in Isolation

Integral part of a Landscape / Street / Complex

Quantification

Area Dimension (LxBxH):

(m / cm/ feet / inch)

Number of Blocks : 01 Number of Story's : 02

Spatial Organization

Orientation : The Temple is oriented North - South and faces the

North.

Plan

Allocation of Spaces :

ARCHITECTURAL STYLE

Ornamentation

Exteriors : Lattice pattern, Toran

Interiors :

Movable Collections

Any Other (specify) :

10. Construction Technology

Structural System : Indo Persian

Building Techniques : Trabeate system and Arcuate

Material of Construction : White stone and plaster

11. Condition Assessment		
In General	Good / Fair Good	
Sign of Deterioration Serious Deterioration Danger of Disappearance	ce	
In Brief (Attach extra sheet if necessary):		
Slightly blackening of surface.		
12. Threats to the Property		
	Natural Negligence Vandalism Urban Pressures	

SECTION III: REFERENCES

13. Reference Sources (published ar	nd unpublished textual details)
Reference	
14. Photographs	
- The state of the	(Attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(Related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
	···-
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS