

# INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments		
1. Name	SECTION I : IDENTIFICATION	Serial No.: RJ/PLI - 135 N
Present Past Other Name (if any): 2. Location	: Char Bhuja jee Mandir : :	
LONGITUDE 74° 20 E	<b>LATITUDE</b> 26° 75 N  Shree Man mohan Parash	ow Noth Mondir Poli Poli
Approach  3. Property Type	<ul> <li>Village (village code)</li> <li>Post : Bali</li> <li>State : Rajasthan</li> <li>The Temple is situated</li> </ul>	·
Buildings  Palace Fort Citadel Govt. building Railway station Defence building Industrial building Other public building Residential building	Religious structures  ✓ Temple  Mosque  Minar  Church  Monastery  Stupa  Tomb, Mausoleum	Other Structures  Wall Gateway Pillar Others (specify)
Engineering structure  Bridge Tunnel Other engineering structure	Open space and related structures  Public square Park or garden Graveyard Baolis, Well Tank Cave	Note: This temple is made upon elevated platform roof of the temple has kangura pattern. It has cloistered verandah. It has pointed arch opening. Sanctum sanctorum sculpture of Lord Charbhuja.

4. Property Use	
	ABANDONED / IN USE: In use
Present	: Religious
Past	: Religious
5. Age (Source)	
PERIOD	:
YEARS	: 17 <sup>th</sup> Century A.D.
Precise date of Construction	:
Completion	:
Subsequent changes	:
Destruction / Demolition	:
6. Ownership / Level of Protection	on
	SINGLE /MULTIPLE :
	:
India / State Archaeology	
Department / Any Other (Please	
specify)	
Private	:
Any other (Please specify)	:
Name	:
Address	:
Phone	•
7. Association	
<ul> <li>WITH EVENTS</li> </ul>	
In History	:
In Rituals	:
In Building Construction	:
Any other (specify)	: Temple
<ul> <li>WITH PERSONS</li> </ul>	
Patron	:
Architect / Engineer	:
Any other (specify)	:
8. Statement of Significance	
Architectural	
Archaeological Historical	
Religious	
	Van suus nattaus
Any other (specify)	Kangura pattern

#### **SECTION II: DESCRIPTION**

#### 9. Physical Description and Decorative Features

• Context \* Drawings (Attach extra sheet if necessary)

**Urban / Rural Setting** 

**Surroundings** 

Rural

Stand in Isolation

Integral part of a Landscape / Street / Complex

Quantification

Area Dimension (LxBxH):

(m / cm/ feet / inch)

Number of Blocks : 01 Number of Story's : 02

Spatial Organization

Orientation : The Temple is oriented North - South and faces the

North.

Plan :

Allocation of Spaces :

### **ARCHITECTURAL STYLE**

Ornamentation

Exteriors : Kangura pattern Interiors : Cloistered verandah

Movable Collections

Any Other (specify) :

#### 10. Construction Technology

Structural System : Indo Persian

**Building Techniques** : Trabeate system and Arcuate

Material of Construction : Stone and plaster

11. Condition Assessment		
In General	Good / Fair Good	
Sign of Deterioration Serious Deterioration Danger of Disappear	n	
In Brief (Attach extra sheet if necessary):		
Plaster peeling off, Blackening of surface.		
12. Threats to the Property		
	Natural Negligence Vandalism Urban Pressures	

## **SECTION III:** REFERENCES

13. Reference Sources (published ar	nd unpublished textual details)
Reference	
14. Photographs	
- in a second second	(Attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(Related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
	···-
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS