

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

	SECTION I : IDENTIFICATION	Serial No.: RJ/PLI - 154
1. Name		
Present Past Other Name (if any):	: Sadan ka well : :	
2. Location		
LONGITUDE 74 ⁰ 20 ['] E	LATITUDE 26 ⁰ 75 ['] N	
Address	Ranakpur Road, Pali	
Approach		District: Pali PIN: 306702 nak Pur in Pali. It is 100 KM is well connected by regular
3. Property Type		
BuildingsPalaceFortCitadelGovt. buildingRailway stationDefence buildingIndustrial buildingOther public buildingsResidential building	Religious structures Temple	Other Structures Wall Gateway Pillar Others (specify) Well
Engineering structure Bridge Tunnel Other engineering structure		te: It is a square shaped deep ter reservoir.

4. Property Use

	ABANDONED / IN USE : In use
Present Past	: Source of water
5. Age (Source)	
PERIOD YEARS Precise date of Construction Completion Subsequent changes Destruction / Demolition	17 th Century A.D.
6. Ownership / Level of Protecti	
	SINGLE /MULTIPLE :
Public : Archaeological Survey of India / State Archaeology Department / Any Other (Please specify)	:
Private	:
Any other (Please specify)	:
Name Address	
Phone	
7. Association	
 WITH EVENTS In History In Rituals In Building Construction Any other (specify) WITH PERSONS	Water reservoir
8. Statement of Significance	
Architectural Archaeological Historical Religious Any other (specify)	Square shaped

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features				
•	Context		* Drawings (Attach extra sheet if n	ecessary)
	Urban / Rural Setting Surroundings		Rural	
			Stand in Isolation Integral part of a Landscape / Str	eet / Complex
•	Quantification Area Dimension (L x B x H)	:		(m / cm/ feet / inch)
	Number of Blocks Number of Story's	:	01 01	
•	Spatial Organization Orientation	:	The Well is oriented East - West ar	nd faces the East.
	Plan	:		
	Allocation of Spaces	:		
ARCHITECTURAL STYLE				

Ornamentation Exteriors Interiors Movable Collections	: Square shaped :
Any Other (specify)	:

10. Construction Technology

Structural System	:	Indo Persian
Building Techniques	:	Trabeate system
Material of Construction	:	Stone and plaster

11. Condition Assessment

In General

Good / Fair Good

Sign of Deterioration Serious Deterioration

Danger of Disappearance

In Brief (Attach extra sheet if necessary):

Breaking of structure, blackening of surface.

12. Threats to the Property



SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
(Attach list as in page 6, in case of multiple photographs	
Photo Reference	
CAPTION	
15. Audio / Video	
	(Related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS