

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments Serial No.: RJ/PLI - 163 **SECTION I: IDENTIFICATION** 1. Name Present Shiv Mandir **Past** Other Name (if any): 2. Location LONGITUDE 74° 20' E 26° 75' N LATITUDE Address Jhalima Chowk, Ghaneran Village (village code) Post: Ghaneran District: Pali State: Rajasthan **PIN:** 306704 The Temple is situated at Ghaneran in Pali. It is 120 Approach KM away from Pali district. It is well connected by regular bus services. 3. Property Type **Buildings** Religious structures **Other Structures** Palace Temple Wall Mosque Fort Gateway Citadel Minar Pillar Govt. building Church Others (specify) Railway station Monastery Defence building Stupa Industrial building Tomb, Mausoleum Other public buildings Residential building Engineering structure Open space and related Note: This is a temple made upon structures an elevated platform. It has Bridge Public square curvilinear superstructure which is Park or garden decorated with multi turrets. It had Tunnel been halfly fallen down. Drum is Other engineering structure Graveyard decorated with kangura pattern. Baolis, Well Tank Cave

4. Property Use	
	ABANDONED / IN USE: Abandoned
Present Past	: : Religious
5. Age (Source)	
PERIOD YEARS Precise date of Construction Completion Subsequent changes Destruction / Demolition	: 17 th Century A.D. :
6. Ownership / Level of Protection	
Public: Archaeological Survey of India / State Archaeology Department / Any Other (Please specify) Private Any other (Please specify) Name Address Phone	SINGLE /MULTIPLE : : : : : : : : : : : : : : : : : : :
7. Association	
 WITH EVENTS In History In Rituals In Building Construction Any other (specify) WITH PERSONS Patron Architect / Engineer Any other (specify) 	: : : : : : : : : : : : : : : : : : :
8. Statement of Significance	
Architectural Archaeological Historical Religious Any other (specify)	Curvilinear superstructure

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features

• Context * Drawings (Attach extra sheet if necessary)

Urban / Rural Setting

Surroundings

Rural

Stand in Isolation

Integral part of a Landscape / Street / Complex

Quantification

Area Dimension (L x B x H):

(m / cm/ feet / inch)

Number of Blocks : 01 Number of Story's : 01

Spatial Organization

Orientation : The Temple is oriented North - South and faces the

South.

Plan :

Allocation of Spaces :

ARCHITECTURAL STYLE

Ornamentation

Exteriors : Curvilinear superstructure, multi turrets

Interiors

Movable Collections

Any Other (specify) :

10. Construction Technology

Structural System : Nagara style

Building Techniques : Trabeate system

Material of Construction : Stone and plaster

11. Condition Assessment			
In General	Good / Fair Fair		
Sign of Deterioration Serious Deterioration Danger of Disappe In Brief (Attach extra s	on earance		
Plaster pooling off Blac	koning of curface due	t and dirt deposition, breaking of building.	
riaster peeling on, blac	keriing or surface, dus	t and dift deposition, breaking or building.	
12. Threats to the Pro	perty		
	Natu	al	
	Negli	gence	
	Vand	-	
		n Pressures	

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(Attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
5/11 116H	
15. Audio / Video	
	(Related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
	17 till 2
18. Reviewers	
NAME	NAME
0011111110	001115150
COMMENTS	COMMENTS