

# INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments		
1. Name	SECTION I: IDENTIFICATION	Serial No.: RJ/PLI - 183
Present Past Other Name (if any): 2. Location	: Suraj Kund : :	
LONGITUDE 74° 20' E	LATITUDE 26° 75' N	
Address		District: Pali PIN: 306704  ar bus stand at Ghaneran in M away from Pali. It is well services.
3. Property Type		
Buildings  Palace Fort Citadel Govt. building Railway station Defence building Industrial building Other public building Residential building	Religious structures  Temple Mosque Minar Church Monastery Stupa Tomb, Mausoleum	Other Structures Wall Gateway Pillar Others (specify)
Engineering structure  Bridge Tunnel Other engineering structure		ote: It is a small water reservoir ith well managed staircases.

4. Property Use	
	ABANDONED / IN USE :
Present Past	: Religious
5. Age (Source)	
PERIOD YEARS Precise date of Construction Completion Subsequent changes Destruction / Demolition  6. Ownership / Level of Protection	: 18 <sup>th</sup> Century A.D. : : : :
	SINGLE /MULTIPLE :
Public: Archaeological Survey of India / State Archaeology Department / Any Other (Please specify) Private Any other (Please specify) Name Address Phone	: : : : :
7. Association	
<ul> <li>WITH EVENTS         <ul> <li>In History</li> <li>In Rituals</li> <li>In Building Construction</li> <li>Any other (specify)</li> </ul> </li> <li>WITH PERSONS         <ul> <li>Patron</li> <li>Architect / Engineer</li> <li>Any other (specify)</li> </ul> </li> </ul>	: : : : : : : : : : : : : : : : : : :
8. Statement of Significance	
Architectural Archaeological Historical Religious Any other (specify)	Water reservoir

### **SECTION II: DESCRIPTION**

### 9. Physical Description and Decorative Features

• Context \* Drawings (Attach extra sheet if necessary)

Urban / Rural Setting Surroundings

Stand in Isolation

Integral part of a Landscape / Street / Complex

Quantification

Area Dimension (LxBxH):

(m / cm/ feet / inch)

Number of Blocks : 01

Number of Story's

• Spatial Organization

Orientation : The Tank is oriented East - West and faces the East.

Plan

Allocation of Spaces :

#### **ARCHITECTURAL STYLE**

Ornamentation

Exteriors : Water reservoir

Interiors :

Movable Collections :

Any Other (specify) :

#### 10. Construction Technology

Structural System : Indo peersian

**Building Techniques** : Trabeate system

Material of Construction : Stone and plaster

11. Condition Assessment		
In General	Good / Fair Good	
Sign of Deterioration Serious Deterioration Danger of Disappearance  In Brief (Attach extra sheet if necessary):		
Blackening of surface, vegetation growth, Dust & dirt depostion.		
12. Threats to the Property		
	Natural Negligence Vandalism Urban Pressures	

# SECTION III: REFERENCES

## 13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(Attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(Related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS