

### INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

#### **Documentation format for Archaeological / Heritage Sites / Monuments** Serial No.: RJ/PLI - 185 **SECTION I: IDENTIFICATION** 1. Name Present Suraj Pol Past Other Name (if any): 2. Location LONGITUDE 74° 20' E 26<sup>0</sup> 75<sup>'</sup> N LATITUDE Address , Suraj Pol, Ghaneran Village (village code) Post: Ghaneran **District**: Pali State: Rajasthan **PIN:** 306704 Approach The Gateway is situated at Ghaneran in Pali. It is 120 KM away from Pali district. It is well connected by regular bus services. 3. Property Type Buildings Religious structures **Other Structures** Palace Temple Wall Fort Mosque Gateway Pillar Citadel Minar Church Govt. building Others (specify) Railway station Monastery Defence building Stupa Industrial building Tomb, Mausoleum Other public buildings Residential building Engineering structure Open space and related Note: It is a massive gateway. It structures has pointed arch opening. It has Bridge Public square parapet wall and bastion. Park or garden Tunnel Other engineering structure Graveyard Baolis, Well Tank Cave

4. Property Use	
	ABANDONED / IN USE: In use
Present	: Gateway
Past	: Gateway
5. Age (Source)	
0.7190 (000.00)	
PERIOD	:
YEARS	: 17 <sup>th</sup> Century A.D.
Precise date of Construction	:
Completion	:
Subsequent changes	:
Destruction / Demolition	
6. Ownership / Level of Protection	on
	SINGLE /MULTIPLE :
Public: Archaeological Survey of	:
India / State Archaeology	
Department / Any Other (Please	
specify) <b>Private</b>	
Any other (Please specify)	•
Name	•
Address	•
Phone	•
7. Association	
WITH EVENTS	
In History	:
In Rituals	:
In Building Construction	:
Any other (specify)	:
<ul> <li>WITH PERSONS</li> </ul>	
Patron	:
Architect / Engineer	:
Any other (specify)	
8. Statement of Significance	
Architectural	
Archaeological	
Historical	
Religious Any other (specify)	Pointed arch

#### **SECTION II: DESCRIPTION**

### 9. Physical Description and Decorative Features

• Context \* Drawings (Attach extra sheet if necessary)

**Urban / Rural Setting** 

Surroundings

Rural

Stand in Isolation

Integral part of a Landscape / Street / Complex

Quantification

Area Dimension (LxBxH):

(m / cm/ feet / inch)

Number of Blocks : 01 Number of Story's : 01

• Spatial Organization

Orientation : The Gateway is oriented East - West and faces the

East.

Plan

Allocation of Spaces :

#### **ARCHITECTURAL STYLE**

Ornamentation

Exteriors : Massive gateway, pointed arch

Interiors :

Movable Collections :

Any Other (specify) :

#### 10. Construction Technology

Structural System : Indo persion

**Building Techniques** : Arcuate

Material of Construction : Stone and plaster

11. Condition Assessment		
In General	Good / Fair Good	
Sign of Deterioration Serious Deterioration Danger of Disappearance  In Brief (Attach extra sheet if necessary): Plaster peeling off, breaking of building, Blackening of surface, Dust and dirt deposition.  12. Threats to the Property		
	Natural Negligence Vandalism Urban Pressures	

# SECTION III: REFERENCES

## 13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(Attach list as in page 6, in case of multiple photographs)
Photo Reference	
0.17	
CAPTION	
15. Audio / Video	
	(Related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
10. Maps/Plans/Drawings	
17. Listers	
NI A BATT	NARGE
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS