


**INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS** 

Janpath, New Delhi -110 001, www.ignca.gov.in

#### Documentation format for Archaeological / Heritage Sites / Monuments

1. Name	SECTION I : IDENTIFICATION	Serial No.: RJ/PLI - 221
Present Past Other Name (if any):	: Al fee gate :	
2. Location		
LONGITUDE 74° 20' E	<b>LATITUDE</b> 26 <sup>0</sup> 75 <sup>°</sup> N	
Address	Chaudhary ka Wash Nadol, Pali	
	: Village (village code) Post : Nadol State : Rajasthan	Nadol District: Pali PIN: 306603
Approach	: The Gateway is situated nea Nadol in Pali District. It is 10 stand.	-
3. Property Type		
Buildings	Religious structures	Other Structures



## 4. Property Use

		ABANDONED / IN USE : In use
Present Past	:	Gateway Gateway
5. Age (Source)		
PERIOD	:	
YEARS	÷	16 <sup>th</sup> Century A.D.
Precise date of Construction	÷	
Completion	:	
Subsequent changes	:	
Destruction / Demolition	:	
6. Ownership / Level of Protection	on	
		SINGLE /MULTIPLE :
Public : Archaeological Survey of	:	
India / State Archaeology		
Department / Any Other (Please		
specify)		
Private	:	
Any other (Please specify)	:	
Name	:	
Address	:	
Phone	:	
7. Association		
WITH EVENTS		
In History	:	
In Rituals	:	
In Building Construction	:	
Any other (specify)	:	Gateway
WITH PERSONS		
Patron	:	
Architect / Engineer	:	
Any other (specify)	:	
8. Statement of Significance		
Architectural		
Archaeological		
Historical		
Religious		

Any other (specify)

Domical superstructure

	Context		* Drawings (Attach extra sheet if necessary)
	Urban / Rural Setting Surroundings		Stand in Isolation Integral part of a Landscape / Street / Complex
•	<b>Quantification</b> Area Dimension ( L x B x H)	:	(m / cm/ feet / inch)
	Number of Blocks Number of Story's	:	01 01
	Spatial Organization Orientation	:	The Gateway is oriented North - South and faces the North.
	Plan	:	
	Allocation of Spaces	:	

# **SECTION II: DESCRIPTION**

### ARCHITECTURAL STYLE

•	Ornamentation Exteriors Interiors Movable Collections	:	Domical superstructure, kangura pattern, chajja
An	<b>y Other</b> (specify)	:	

# 10. Construction Technology

Structural System	:	Indo persian
Building Techniques	:	Trabeate system
Material of Construction	:	Stone and plaster

## 11. Condition Assessment

#### In General

**Good / Fair** Good

Sign of Deterioration Serious Deterioration Danger of Disappearance

## In Brief (Attach extra sheet if necessary):

Dust and Dirt deposition.

## 12. Threats to the Property



# SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(Attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(Related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS