


INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

1. Name	SECTION I : IDENTIFICATION	Serial No.: RJ/PLI - 301
Present Past Other Name (if any):	: Sati Mata ki chhatri : :	
2. Location		
LONGITUDE 74 ⁰ 20 [°] E	LATITUDE 26 ⁰ 75 ['] N	
Address	Shree Sela	
	: Village (village code) Post : Shree Sela State : Rajasthan	Shree Sela District: Pali PIN: 306701
Approach		Shree Sela in Pali District. It ali. It is well connected by
3. Property Type		
Buildings	Religious structures	Other Structures



4. Property Use

		ABANDONED / IN USE :
Present	:	Memorial
Past	:	Memorial
5. Age (Source)		
PERIOD	:	the second se
YEARS	:	17 th Century A.D. (Renovated)
Precise date of Construction	:	
Completion	:	
Subsequent changes	÷	
Destruction / Demolition	:	
6. Ownership / Level of Protection	on	
		SINGLE /MULTIPLE :
Public : Archaeological Survey of	:	
India / State Archaeology		
Department / Any Other (Please		
specify)		
Private	:	
Any other (Please specify)	÷	
Name Address	÷	
Phone		
Phone	•	
7. Association		
WITH EVENTS		
In History	:	
In Rituals	:	
In Building Construction	:	
Any other (specify)	:	
WITH PERSONS		
Patron	:	
Architect / Engineer	:	
Any other (specify)	:	
8. Statement of Significance		
o. Statement of Significance		

Architectural Archaeological Historical Religious Any other (specify)

SECTION II: DESCRIPTION

•	Context		* Drawings (Attach extra sheet if necessary)
	Urban / Rural Setting Surroundings		Rural
	ourroundings		Stand in Isolation Integral part of a Landscape / Street / Complex
•	Quantification Area Dimension (L x B x H)	:	(m/om/fact/inch)
	Number of Blocks Number of Story's	:	(m / cm/ feet / inch) 01 01
•	Spatial Organization Orientation	:	The chhatri is oriented North - South and faces the South.
	Plan	:	
	Allocation of Spaces	:	

Ornamentation		
Exteriors	:	Pyramidal chhatri
Interiors	:	
Movable Collections	:	
Any Other (specify)	:	

10. Construction Technology

Structural System Building Techniques	:	Trabeate system
Material of Construction	:	Stone

11. Condition Assessment

In General

Good / Fair

✓ Sign of Deterioration

Serious Deterioration

Danger of Disappearance

In Brief (Attach extra sheet if necessary):

Well maintained

12. Threats to the Property

✓	Natural
	Negligence
	Vandalism
	Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(Attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(Related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS