

# INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS Janpath, New Delhi -110 001, www.ignca.gov.in

# **Documentation format for Archaeological / Heritage Sites / Monuments**

Serial No.:RJ/PTG-004

1. Name	SECTION I: IDENTIFICATION	ı
Present Past Other Name (if any):	: Gordhan Nath Mandir : :	
2. Location		
LONGITUDE 74°78'E	LATITUDE	24° 03′N
Address	Gopalganj ,Pratapgarh	
Approach district	•	District: Pratapgarh PIN: 312605  at Gopalganj in Pratapgarh n Pratapgarh bus stand. It is lar bus services.
3. Property Type		
Buildings Palace Fort Citadel Govt. building Railway station Defence building Industrial building Other public building Residential building	Religious structures  √ Temple     Mosque     Minar     Church     Monastery     Stupa     Tomb, Mausoleum	Other Structures  Wall Gateway Pillar Others (specify)
Engineering structure	Open space and related structures	<b>Note:</b> This is a temple which is in a ruined state. The structural elements fallen down here and there. Stone images of Elephant are seen near the ruined temple.
Bridge Tunnel Other engineering structure	Public square Park or garden Graveyard Baolis, Well Tank	and a source and runned temple.

## 4. Property Use

#### ABANDONED / IN USE

Present : Religious Past : Religious

5. Age (Source)

PERIOD : 16<sup>th</sup> Century AD

YEARS :

Precise date of Construction :
Completion :
Subsequent changes :
Destruction / Demolition :

### 6. Ownership / Level of Protection

#### **SINGLE /MULTIPLE:**

**Public**: Archaeological Survey of :

India / State Archaeology

Department / Any Other (Please

specify)state Govt.

Private : Any other (Please specify) : Name : Address : Phone :

#### 7. Association

#### •1 WITH EVENTS

In History :
In Rituals :
In Building Construction :
Any other (specify) :

•2 WITH PERSONS

Patron :
Architect / Engineer :
Any other (specify) :

# 8. Statement of Significance

<ul> <li>✓ Architectural</li> <li>Archaeological</li> <li>Historical</li> <li>Religious</li> <li>Any other (specify)</li> </ul>	:	Dilapidated temple having stone image of elephants.
<u> </u>	SEC	CTION II: DESCRIPTION
9. Physical Description and Dec	cor	ative Features
•3 Context Urban √/ Rural Setting Surroundings		* Drawings (Attach extra sheet if necessary)
		Stand in Isolation Integral part of a Landscape / Street / Complex
•4 Quantification Area Dimension ( L x B x H)	:	
Number of Blocks Number of Storys	:	(m / cm/ feet / inch) 01 01
•5 Spatial Organization Orientation Plan	:	The Temple is oriented North/South and faces the North.
Allocation of Spaces	:	
ARCHITECTURAL STYLE  •6 Ornamentation Exteriors Interiors Movable Collections Any Other (specify)	: : : : : : : : : : : : : : : : : : : :	Painted stone image of elephants.
10. Construction Technology		
Structural System Building Techniques Material of Construction	: : :	Temple made up of stone and brick Masonry work. stone, brick

11. Condition Assessment	
In General	Good /√ Fair
	Sign of Deterioration Serious Deterioration Danger of Disappearance
In Brief (Attach extra sheet	if necessary): Badly damaged.
12. Threats to the Property	
	<ul><li>√ Natural</li><li>Negligence</li><li>Vandalism</li><li>Urban Pressures</li></ul>

## **SECTION III:** REFERENCES

Udaipur Sambhag Ka Jilewar Sanskritik Aur Etihasik Adhyayan, Dr. Mohan Lal Gupta, 2009, Rajasthani Granthagar-Jodhpur

14. Photographs

(attach list as in page 6, in case of multiple photographs)

Photo Reference CAPTION

15. Audio / Video

(related to rituals / performance / festivals etc.)

Reference DESCRIPTION

16. Maps/Plans/Drawings

17. Listers

NAME NAME

18. Reviewers

NAME NAME

COMMENTS COMMENTS