



# INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

## Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.:RJ/PTG-068

### SECTION I : IDENTIFICATION

#### 1. Name

Present : Nana Mata Mandir  
 Past :  
 Other Name (if any): :

#### 2. Location

LONGITUDE LATITUDE

#### Address

Nana Mata Temple Talab Pratapgarh

: **Village (village code)**  
**Post:** Pratapgarh **District:** Pratapgarh  
**State:** Rajasthan **PIN:** 312605

#### Approach district

: The Temple is situated in Talab Pratapgarh district. It is 3km away from Bus stand, Pratapgarh. It is well connected by regular bus services.

#### 3. Property Type

##### **Buildings**

- Palace
- Fort
- Citadel
- Govt. building
- Railway station
- Defence building
- Industrial building
- Other public buildings
- Residential building

##### **Religious structures**

- Temple
- Mosque
- Minar
- Church
- Monastery
- Stupa
- Tomb, Mausoleum

##### **Other Structures**

- Wall
- Gateway
- Pillar
- Others (specify)

##### **Engineering structure**

- Bridge
- Tunnel
- Other engineering structure

##### **Open space and related structures**

- Public square
- Park or garden
- Graveyard
- Baolis, Well

**Note:** It is a small temple having domes on top of it. The temple is painted with pink color. The entrance to the temple is thought an iron-grill-door. Images of deities and framed photographs adorned the 'Garbha-griha'

Tank  
 Cave

#### 4. Property Use

**ABANDONED / IN USE**

**Present** : Religious  
**Past** : Religious

#### 5. Age (Source)

**PERIOD** : 19<sup>th</sup> Century AD  
**YEARS** :  
**Precise date of Construction** :  
**Completion** :  
**Subsequent changes** :  
**Destruction / Demolition** :

#### 6. Ownership / Level of Protection

**SINGLE / MULTIPLE :**

**Public** : Archaeological Survey of India / State Archaeology Department / Any Other (Please specify)state Govt. :  
**Private** :  
**Any other (Please specify)** :  
**Name** :  
**Address** :  
**Phone** :

#### 7. Association

##### •1 WITH EVENTS

**In History** :  
**In Rituals** :  
**In Building Construction** :  
**Any other (specify)** :

##### •2 WITH PERSONS

**Patron** :  
**Architect / Engineer** :  
**Any other (specify)** :

#### 8. Statement of Significance

Architectural

Temple having dome on top of it.



## 11. Condition Assessment

In General

Good ✓/ Fair

- |                          |                         |
|--------------------------|-------------------------|
| <input type="checkbox"/> | Sign of Deterioration   |
| <input type="checkbox"/> | Serious Deterioration   |
| <input type="checkbox"/> | Danger of Disappearance |

**In Brief (Attach extra sheet if necessary):** Blackening of the surface, floors are dirty, cracks, deposition of sooth. etc.

## 12. Threats to the Property

- |                                     |                 |
|-------------------------------------|-----------------|
| <input checked="" type="checkbox"/> | Natural         |
| <input type="checkbox"/>            | Negligence      |
| <input type="checkbox"/>            | Vandalism       |
| <input type="checkbox"/>            | Urban Pressures |

### **SECTION III: REFERENCES**

**13. Reference Sources** (published and unpublished textual details)

**14. Photographs**

(attach list as in page 6, in case of multiple photographs)

**Photo Reference  
CAPTION**

**15. Audio / Video**

(related to rituals / performance / festivals etc.)

**Reference  
DESCRIPTION**

**16. Maps/Plans/Drawings**

**17. Listers**

**NAME**

**NAME**

**18. Reviewers**

**NAME  
COMMENTS**

**NAME  
COMMENTS**