

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.:RJ/PTG-078

1. Name	SECTION I: IDENTIFICATIO	N		
Present Past Other Name (if any):	: Bawari Ka Gateway : :			
2. Location				
LONGITUDE 74°78'E	LATITUDE	24°03'N		
Address	Tai Darwaja Chapnath roa	Tai Darwaja Chapnath road Pratagarh		
	: Village (village code) Post: Pratapgarh State: Rajasthan	District: Pratapgarh PIN: 312605		
Approach district		lear Tai Darwaja in Pratapgarh I stand, Pratapgarh. It is well bus services.		
3. Property Type				
Buildings Palace Fort Citadel Govt. building Railway station Defence building Industrial building Other public building Residential building	Religious structures Temple Mosque Minar Church Monastery Stupa Tomb, Mausoleum	Other Structures Wall √ Gateway Pillar Others (specify)		
Engineering structure	Open space and related structures	Note: The Gateway has semi-circular arch opening. Cracks have been developed on the ceiling of the gateway. The other end of the gateway has foliated arhed opening.		
Bridge Tunnel Other engineering structure	Public square Park or garden Graveyard Baolis, Well Tank Cave			

4. Property Use

ABANDONED √/ IN USE

Present : Gateway Past : Gateway

5. Age (Source)

PERIOD : 18th Century AD

YEARS :

Precise date of Construction Completion Subsequent changes Destruction / Demolition

6. Ownership / Level of Protection

SINGLE /MULTIPLE:

Public: Archaeological Survey of :

India / State Archaeology

Department / Any Other (Please

specify)state Govt.

Private : Any other (Please specify) : Name : Address : Phone :

7. Association

•1 WITH EVENTS

In History : In Rituals : In Building Construction : Any other (specify) :

•2 WITH PERSONS

Patron : Architect / Engineer : Any other (specify) :

8. Statement of Significance						
 ✓ Architectural Archaeological Historical Religious Any other (specify) 	G:	ateway having semi-circular arch opening.				
SECTION II: DESCRIPTION						
9. Physical Description and Dec	cora	tive Features				
•3 Context Urban √/ Rural Setting Surroundings		* Drawings (Attach extra sheet if necessary)				
		Stand in Isolation Integral part of a Landscape / Street / Complex				
•4 Quantification Area Dimension (L x B x H)	:					
Number of Blocks Number of Storys	:	(m / cm/ feet / inch)				
•5 Spatial Organization Orientation Plan Allocation of Spaces	: : :	The Gate is oriented North/South and faces the South				
•6 Ornamentation Exteriors Interiors	:					
Movable Collections Any Other (specify)	:					
10. Construction Technology						

Structural System: Indo-PersianBuilding Techniques: Arcuate systemMaterial of Construction: stone

11. Condition Assessment			
In General	Good / √Fair		
	Sign of Deterioration Serious Deterioration Danger of Disappearance		
In Brief (Attach extra sheet	if necessary): Pilling of plaster, blackening etc.		
12. Threats to the Property			
	√ NaturalNegligenceVandalismUrban Pressures		

SECTION III: REFERENCES

13. Reference Sources	(published and unp	ublished textual	details)

14. Photographs(attach list as in page 6, in case of multiple photographs)

Photo Reference CAPTION

15. Audio / Video (related to rituals / performance / festivals etc.)

Reference DESCRIPTION

16. Maps/Plans/Drawings

17. Listers

NAME NAME

18. Reviewers

NAME NAME

COMMENTS COMMENTS