

Documentation format for Archaeological / Heritage Sites / Monuments


Serial No.:RJ/PTG-080

SECTION I: IDENTIFICATION

Chap Nath Ki Bawari	
LATITUDE	24°03'N
ai Darwaja, Chapnath Temple road	
: Village (village code) Post: Pratapgarh State: Rajasthan	District: Pratapgarh PIN: 312605
	ear Chapnath Mahadev s 2km away from Pratapgarh ected by regular bus services.
	LATITUDE Tai Darwaja, Chapnath Temp : Village (village code) Post: Pratapgarh State: Rajasthan : The Bawari is situated ne Mandir in Pratapgarh. It is

3. Property Type

1 Name



4. Property Use

ABANDONED / VIN USE

SINGLE /MULTIPLE :

Present	:	Step well
Past	:	Source of water

5. Age (Source)

PERIOD	:	18 th Century AD
YEARS	:	-
Precise date of Construction	:	
Completion	:	
Subsequent changes	:	
Destruction / Demolition	:	

6. Ownership / Level of Protection

Public : Archaeological Survey of India / State Archaeology	:
Department / Any Other (Please	
specify)state Govt.	
Private	:
Any other (Please specify)	:
Name	:
Address	:
Phone	:

7. Association

•1 WITH EVENTS

In History	:
In Rituals	:
In Building Construction	:
Any other (specify)	:
•2 WITH PERSONS	
Patron	:
Architect / Engineer	:
Any other (specify)	:

8. Statement of Significance

Architectural
Archaeological
Historical
Religious
Any other (specify)

SECTION II: DESCRIPTION

:

9. Physical Description and Decorative Features			
●3 Context Urban √/ Rural Setting Surroundings	* Drawings (Attach extra sheet if necessary)		
	Stand in Isolation Integral part of a Landscape / Street / Complex		
•4 Quantification Area Dimension (L x B x H)			
Number of Blocks Number of Storys	(m / cm/ feet / inch) 0		
•5 Spatial Organization Orientation Plan Allocation of Spaces	The Bawari is oriented East/West and faces the West.		
ARCHITECTURAL STYLE •6 Ornamentation Exteriors Interiors Movable Collections Any Other (specify)			
10. Construction Technology			
Structural System Building Techniques	Rectangular step well made Masonry works		

ding Techniques	:	Masonry works

	-	
Material of Construction	:	Rubble masonry and stone.

11. Condition Assessment

In General

 $\mathbf{Good} \sqrt{\mathbf{/}} \mathbf{Fair}$

Sign of DeteriorationSerious DeteriorationDanger of Disappearance

In Brief (Attach extra sheet if necessary): Pilling of plaster, cracks, broken staircases and Vegetational growth.

12. Threats to the Property



SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
Dhafa Dafammaa	(attach list as in page 6, in case of multiple photographs)
Photo Reference CAPTION	
15. Audio / Video	(related to rituals / performance / festivals etc.)
Reference DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
ΝΔΜΕ	ΝΔΜΕ

NAME COMMENTS NAME COMMENTS