

Documentation format for Archaeological / Heritage Sites / Monuments

#### Serial No.:RJ/PTG-081

#### **SECTION I: IDENTIFICATION**

1. Name		
Present Past Other Name (if any):	: Suraj Kund :	
2. Location		
LONGITUDE 74°78'E	LATITUDE	24°03'N
Address	Near, Tai Darwaja, Chapn	ath Temple road Pratapgarh.
	: Village (village code) Post: Pratapgarh State: Rajasthan	<b>District:</b> Pratapgarh <b>PIN:</b> 312605
Approach district	Pratapgarh. It is 2km a	near Chapnath Mandir in away from bus stand, connected by regular bus
3. Property Type		
BuildingsPalaceFortCitadelGovt. buildingRailway stationDefence buildingIndustrial buildingOther public buildingsResidential building	Religious structuresTempleMosqueMinarChurchMonasteryStupaTomb, Mausoleum	Other Structures         Wall         Gateway         Pillar         √         Others (specify)         Kund
Engineering structure	Open space and related structures	<b>Note:</b> It is a circular well cladded with rubble masonry. Iron-pipes are attached to the well the
Bridge Tunnel Other engineering structure	<ul> <li>Public square</li> <li>Park or garden</li> <li>Graveyard</li> <li>Baolis, Well</li> <li>Tank</li> <li>Cave</li> </ul>	fetching water.

4. Property Use

# ABANDONED $\sqrt{I}$ IN USE

Present	:	Well
Past	:	Well

# 5. Age (Source)

PERIOD	:	19 <sup>th</sup> Century AD
YEARS	:	-
Precise date of Construction	:	
Completion	:	
Subsequent changes	:	
<b>Destruction / Demolition</b>	:	

# 6. Ownership / Level of Protection

# SINGLE /MULTIPLE :

<b>Public</b> : Archaeological Survey of India / State Archaeology Department / Any Other (Please specify)state Govt.	:
Private	:
Any other (Please specify)	:
Name	:
Address	:
Phone	:

#### 7. Association

#### •1 WITH EVENTS

In History	1
In Rituals	:
In Building Construction	
Any other (specify)	
•2 WITH PERSONS	
Patron	
Architect / Engineer	
Any other (specify)	:

# 8. Statement of Significance

1	
1	
ŀŀ	

Architectural Archaeological Historical Circular well

Religious Any other (specify)

:

# **SECTION II: DESCRIPTION**

9. Physical Description and Dec	cor	ative Features	
●3 Context Urban √/ Rural Setting Surroundings		* Drawings (Attach extra sheet if necessary)	
		Stand in Isolation Integral part of a Landscape / Street / Complex	
•4 Quantification Area Dimension ( L x B x H)	:	(m / cm/ feet / inch)	
Number of Blocks Number of Storys	:		
•5 Spatial Organization Orientation Plan Allocation of Spaces	:	The Kund is oriented East/West and faces the West	
ARCHITECTURAL STYLE •6 Ornamentation Exteriors Interiors Movable Collections Any Other (specify)	::	Circular well cladded with rubble masonry	
10. Construction Technology			
Structural System	:	Indo-Persian	

Structural System	:	Indo-Persian
Building Techniques	:	Rubble masonry
Material of Construction	:	stone and plaster

#### **11. Condition Assessment**

In General

Good √/ Fair



Sign of Deterioration Serious Deterioration Danger of Disappearance

In Brief (Attach extra sheet if necessary): Cracks, peeling of plaster and Vegetational growth.

### **12. Threats to the Property**



# **SECTION III:** REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
Dhafa Dafammaa	(attach list as in page 6, in case of multiple photographs)
Photo Reference CAPTION	
15. Audio / Video	(related to rituals / performance / festivals etc.)
Reference DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
ΝΔΜΕ	ΝΔΜΕ

NAME COMMENTS NAME COMMENTS