

## Documentation format for Archaeological / Heritage Sites / Monuments

#### Serial No.:RJ/PTG-090

rubble

#### **SECTION I**: IDENTIFICATION

1. Name		
Present Past Other Name (if any):	: Bagghala Bawari : :	
2. Location		
LONGITUDE 74°78'E	LATITU	<b>JDE</b> 24°03'N
Address	Out of Bhatpura Darwaja	a Pratapgarh
	: Village (village cod Post: Pratapgarh State: Rajasthan	e) District: Pratapgarh PIN: 312605
Approach district	Pratapgarh. It is 2km	ed out of Bhatpura Darwaja in away from Bus stand, connected by regular bus
3. Property Type		
BuildingsPalaceFortCitadelGovt. buildingRailway stationDefence buildingIndustrial buildingOther public buildingsResidential building	Religious structuresTempleMosqueMinarChurchMonasteryStupaTomb, Mausoleum	Other Structures         Wall         Gateway         Pillar         √         Others (specify)         Bawari
Engineering structure	<i>Open space and related structures</i>	<b>Note:</b> It is a step well in a dilapidated state. The well is dried and full of Vegetational growth. The well is surrounded by boundary wall Cladded with rubble
Bridge Tunnel Other engineering structure	<ul> <li>Public square</li> <li>Park or garden</li> <li>Graveyard</li> <li>Baolis, Well</li> <li>Tank</li> </ul>	masonry.

Cave

4. Property Use

# 

Present	:
Past	:

## 5. Age (Source)

PERIOD	:	18th Century AD
YEARS	:	
Precise date of Construction	:	
Completion	:	
Subsequent changes	:	
Destruction / Demolition	:	

# 6. Ownership / Level of Protection

SINGLE /MULTIPLE :

<b>Public</b> : Archaeological Survey of India / State Archaeology Department / Any Other (Please	:
specify)state Govt. Private	
Any other (Please specify)	:
Name	:
Address	:
Phone	:

## 7. Association

#### 8. Statement of Significance

Well Cladded with rubble masonry.

Architectural Archaeological

 $\sqrt{}$ 

	Historical
	Religious
	Any other (specify)

# **SECTION II: DESCRIPTION**

:

9. Physical Description and Decorative Features			
●3 Context Urban √/ Rural Setting Surroundings		* Drawings (Attach extra sheet if necessary)	
Carroananigo		Stand in Isolation Integral part of a Landscape / Street / Complex	
•4 Quantification			
Area Dimension (L x B x H)	:		
		(m / cm/ feet / inch)	
Number of Blocks	÷		
Number of Storys	•		
•5 Spatial Organization			
Orientation	:	The Bawari is oriented East/West and faces the West	
Plan	:		
Allocation of Spaces	:		
ARCHITECTURAL STYLE			
•6 Ornamentation			
Exteriors	:	Step well cladded with rubble masonry.	
Interiors	:		
Movable Collections	:		
Any Other (specify)	:		
10. Construction Technology			
Structural System	:	well made up of Rubble masonry	
Building Techniques Material of Construction	:	Rubble masonry.	
Material of Construction	:	Rubble masonry.	

# **11. Condition Assessment**

In General

Good / $\sqrt{}$  Fair



Sign of Deterioration Serious Deterioration Danger of Disappearance

In Brief (Attach extra sheet if necessary): Badly damaged

# **12. Threats to the Property**



# **SECTION III:** REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
Dhafa Dafammaa	(attach list as in page 6, in case of multiple photographs)
Photo Reference CAPTION	
15. Audio / Video	(related to rituals / performance / festivals etc.)
Reference DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
ΝΔΜΕ	ΝΔΜΕ

NAME COMMENTS NAME COMMENTS