

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.:RJ/PTG-092

SECTION I: IDENTIFICATION

1. Name		
Present Past Other Name (if any):	: Kesharia Jee Ka well :	
2. Location		
LONGITUDE 74°78'E	LATITUDE 24°03'N	
Address	Kesharia Rai ka Well out of Bhatpura Darwaja Pratapga	arh.
	: Village (village code) Pratapgarh Post: Pratapgarh District: Pratapgarh State: Rajasthan PIN: 312605	
Approach district	: The Well is situated out of Bhatpura Darwaja in Pratapgarh district. It is 3km away from Bus stand, Pratapgarh. It is well connected by regular bus services.	
3. Property Type		
Buildings Palace Fort Citadel Govt. building Railway station Defence building Industrial building Other public buildings Residential building	Religious structuresOther StructuresTempleWallMosqueGatewayMinarPillarChurchOthers (specify)MonasteryStupaTomb, Mausoleum	
Engineering structure	Open space and related structuresNote: It is a step well having descending staircases. The we no longer in use. It is being use as a damping yard. The well is cladded with rubble masonry at	ed
Bridge Tunnel Other engineering structure	plaster. Public square Park or garden Graveyard √ Baolis, Well Tank	

Cave

4. Property Use

SINGLE /MULTIPLE :

Present	:
Past	:

5. Age (Source)

PERIOD	:	18th Century AD
YEARS	:	
Precise date of Construction	:	
Completion	:	
Subsequent changes	:	
Destruction / Demolition	:	

::

::

6. Ownership / Level of Protection

Public : Archaeological Survey of
India / State Archaeology
Department / Any Other (Please
specify)state Govt.:Private:Any other (Please specify):Name:Address:Phone:7. Association

•1 WITH EVENTS
In History
In Rituals
In Building Construction
Any other (specify)
•2 WITH PERSONS
Patron
Architect / Engineer
Any other (specify)

8. Statement of Significance

Step well cladded with rubble masonry.

√ Architectural
 Archaeological
 Historical
 Religious
 Any other (specify)

SECTION II: DESCRIPTION

:

9. Physical Description and Decorative Features			
●3 Context Urban √/ Rural Setting		* Drawings (Attach extra sheet if necessary)	
Surroundings		Stand in Isolation Integral part of a Landscape / Street / Complex	
•4 Quantification Area Dimension (L x B x H)	:	(m / cm/ feet / inch)	
Number of Blocks Number of Storys	:		
•5 Spatial Organization Orientation Plan Allocation of Spaces	:	The Well is oriented East/West and faces the East.	
ARCHITECTURAL STYLE •6 Ornamentation Exteriors Interiors Movable Collections Any Other (specify)	:	Step well cladded with rubble masonry. No	
10. Construction Technology			

Structural System	:	Step well having walls made up of rubble masonry.
Building Techniques	:	
Material of Construction	:	Rubble masonry

11. Condition Assessment

In General

Good √/ Fair

Sign of Deterioration Serious Deterioration Danger of Disappearance

In Brief (Attach extra sheet if necessary): Extremely ruined state.

12. Threats to the Property



SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
Dhafa Dafammaa	(attach list as in page 6, in case of multiple photographs)
Photo Reference CAPTION	
15. Audio / Video	(related to rituals / performance / festivals etc.)
Reference DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
ΝΔΜΕ	ΝΔΜΕ

NAME COMMENTS NAME COMMENTS