


Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.:RJ/PTG-102

SECTION I: IDENTIFICATION

1. Name					
Present Past Other Name (if a		:	Ram Mandir Ka Ga	teway	
2. Location					
LONGITUDE	74°78'E		LATITUDE	24°0	3'N
Address		Rai	m Temple Devgarh		
		:	Village (village coo Post: Devgarh State: Rajasthan	de)	Devgarh District: Pratapgarh PIN: 312621
Approach distric	t	:		n Prat	evgarh in Pratapgarh district. apgarh. It is well connected

3. Property Type



4. Property Use

ABANDONED / VIN USE

Present	:	Gateway
Past	:	Gateway

5. Age (Source)

PERIOD	:	15 th Century AD
YEARS	:	
Precise date of Construction	:	
Completion	:	
Subsequent changes	:	
Destruction / Demolition	:	

:

6. Ownership / Level of Protection

SINGLE /MULTIPLE :

Public : Archaeological Survey of	:
India / State Archaeology	
Department / Any Other (Please	
specify)state Govt.	
Private	:
Any other (Please specify)	:
Name	:
Address	:

7. Association

Phone

•1 WITH EVENTS	
In History	:
In Rituals	:
In Building Construction	:
Any other (specify)	:
•2 WITH PERSONS	
Patron	:
Architect / Engineer	:
Any other (specify)	:

8. Statement of Significance

 Architectural	Pointed arch opening.
Archaeological	
Historical	
Religious	
Any other (specify)	:

SECTION II: DESCRIPTION	
-------------------------	--

9. Physical Description and De	cora	tive Features		
●3 Context Urban √/ Rural Setting Surroundings		* Drawings (Attach extra sheet if necessary)		
		Stand in Isolation Integral part of a Landscape / Street / Complex		
•4 Quantification Area Dimension (L x B x H)	:	(m / cm/ feet / inch)		
Number of Blocks Number of Storys	:			
•5 Spatial Organization Orientation Plan Allocation of Spaces	:	The Gate is oriented East/West and faces the East		
ARCHITECTURAL STYLE •6 Ornamentation Exteriors Interiors Movable Collections Any Other (specify)	:	Battle mented parapet.		
10. Construction Technology				

Structural System	:	Indo-Persian
Building Techniques	:	Arcuate system
Material of Construction	-	Stone and rubble masonry.

11. Condition Assessment

In General

Good√ / Fair

Sign of Deterioration Serious Deterioration Danger of Disappearance

In Brief (Attach extra sheet if necessary): Badly damage, Vegetational growth.

12. Threats to the Property



SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
Dhafa Dafammaa	(attach list as in page 6, in case of multiple photographs)
Photo Reference CAPTION	
15. Audio / Video	(related to rituals / performance / festivals etc.)
Reference DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
ΝΔΜΕ	ΝΔΜΕ

NAME COMMENTS NAME COMMENTS