Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.:RJ/PTG-128

SECTION I: IDENTIFICATION 1. Name **Present** Bawari **Past** Other Name (if any): 2. Location LONGITUDE LATITUDE **Address** Udaipur Road, Devgarh Village (village code) Devgarh Post: Devgarh **District**: Pratapgarh State: Rajasthan **PIN**: 312621 **Approach district** The Bawari is situated at Devgarh in Pratapgarh district. It is 12km away from Pratapgarh. It is well connected by regular bus Services. 3. Property Type **Buildings** Religious structures Other Structures Palace Temple Wall Fort Mosque Gateway Minar Pillar Citadel Govt. building Church Others (specify) Railway station Monastery Defence building Stupa Industrial building Tomb, Mausoleum Other public buildings Residential building Engineering structure Open space and related Note: It is rectangular step well structures cladded with rubble masonry. The well is abandoned and is in ruined state. Bridge Public square Park or garden Tunnel Other engineering structure Graveyard Baolis, Well

Tank Cave

4. Property Use

ABANDONED√ / IN USE

Present Past	:	Source of water.
5. Age (Source)		
PERIOD YEARS Precise date of Construction Completion Subsequent changes Destruction / Demolition	: : : : : : : : : : : : : : : : : : : :	17 th Century AD
6. Ownership / Level of Protection	n	CINCLE (MIII TIDLE).
		SINGLE /MULTIPLE :
Public: Archaeological Survey of India / State Archaeology Department / Any Other (Please specify)state Govt. Private Any other (Please specify) Name Address Phone	: : : : : : : : : : : : : : : : : : : :	
7. Association		
•1 WITH EVENTS In History In Rituals In Building Construction Any other (specify) •2 WITH PERSONS Patron Architect / Engineer Any other (specify)	: : : : : : : : : : : : : : : : : : : :	
8. Statement of Significance		
 ✓ Architectural Archaeological Historical Religious Any other (specify) 	Red	ctangular step well cladded with rubble masoniry.

SECTION II: DESCRIPTION

9. Physical Description and Deco	rative Features	
•3 Context Urban / √Rural Setting Surroundings	* Drawings (Attach extra sheet if necessary)	
oun oununge	Stand in Isolation Integral part of a Landscape / Street / Complex	
•4 Quantification Area Dimension (L x B x H) :	(m / cm/ feet / inch)	
Number of Blocks : Number of Storys :		
•5 Spatial Organization Orientation : Plan : Allocation of Spaces :	The Bawari is oriental North/South and faces the North .	
•6 Ornamentation Exteriors : Interiors : Movable Collections :		
Any Other (specify) : 10. Construction Technology		
Structural System : Building Techniques : Material of Construction :	Rectangular step well cladded with rubble masonry	

11. Condition Assessment	:
In General	Good√ / Fair
	Sign of Deterioration Serious Deterioration Danger of Disappearance
In Brief (Attach extra she	et if necessary): Pilling of plaster, cracks, chipping of stomes and
Vegetational growth	
12. Threats to the Property	<i>1</i>
	√Natural Negligence Vandalism Urban Pressures

SECTION III: REFERENCES

13. Reference Sources	(published and unp	ublished textual	details)

14. Photographs(attach list as in page 6, in case of multiple photographs)

Photo Reference CAPTION

15. Audio / Video (related to rituals / performance / festivals etc.)

Reference DESCRIPTION

16. Maps/Plans/Drawings

17. Listers

NAME NAME

18. Reviewers

NAME NAME

COMMENTS COMMENTS