

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS


Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/PGT-142

1. Name	SECTION I : IDENTIFICATION
Present Past Other Name (if any):	Shani Maharaj ka Mandir
2. Location	
LONGITUDE 74°78'E	LATITUDE 24°03'N
Address	Shari Maharaj Temple, pratapgarh
Approach	 Village (village code) Post : Pratapgarh State : Rajasthan The temple is situated near by Shari Maharaj Temple in Pratapgarg district. It is 2km away from bus stand, Pratapgarh. It is well connected by regular bus services.

3. Property Type



4. Property Use

ABANDONED√/ IN USE

SINGLE /MULTIPLE :

:

Present	:	Religious
Past	:	Religious

5. Age (Source)

PERIOD	:	18th century AD
YEARS	:	
Precise date of Construction	:	
Completion	:	
Subsequent changes	:	
Destruction / Demolition	:	

6. Ownership / Level of Protection

Public : Archaeological Survey of
India / State Archaeology
Department / Any Other (Please
specify):Private:Any other (Please specify):Name:Address:Phone:

7. Association

• WITH EVENTS In History : In Rituals : In Building Construction : Any other (specify) : WITH PERSONS Patron : **Architect / Engineer** : Any other (specify) :

8. Statement of Significance

Architectural
Archaeological
Historical
Religious
Any other (specify)

9. Physical Description and Decorative Features			
•	Context Urban / Rural Setting Surroundings		* Drawings (Attach extra sheet if necessary)
	-		Stand in Isolation Integral part of a Landscape / Street / Complex
•	Quantification Area Dimension (L x B x H)	:	(m / om / fact / inch)
	Number of Blocks Number of Storys	:	(m / cm/ feet / inch) 01 01
•	Spatial Organization Orientation Plan Allocation of Spaces	:	The temple is oriented east /west and faces the east.
<u>A</u> F •	RCHITECTURAL STYLE Ornamentation Exteriors		
Ar	Interiors Movable Collections ny Other (specify)	:	

10. Construction Technology

Structural System	:	Rectangular temple made up of stone and plaster.
Building Techniques Material of Construction	:	Masonry works. Stone and Plaster

11. Condition Assessment

In General

Good √/ Fair

Sign of Deterioration Serious Deterioration

Danger of Disappearance

In Brief (Attach extra sheet if necessary):

Chipping of stone, cracks, pilling of plaster and Vegetational growth.

12. Threats to the Property

✓ Natural
 Negligence
 Vandalism
 Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS