

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS


Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/PGT-147

1. Name	SECTION I : IDENTIFICATION	
Present Past Other Name (if any):	: Bhairo ji ka Mandir :	
2. Location		
LONGITUDE 74°78'E	LATITUDE 24°03'N	
Address	Guptganga Mahadev Temple	
	: Village (village code) Post : Pratapgarh State : Rajasthan District: Pratapgarh PIN: 312605	
Approach	 The Temple is situated near by Gupta Ganga hanuman ji Mandir in Pratapgarh. It is 3km away from Pratapgarh bus stand. It is well connected by regular bus services. 	

3. Property Type



4. Property Use

ABANDONED√/ IN USE

:

Present Past	Religious Religious
Past	Religious

5. Age (Source)

PERIOD YEARS	:	19th century AD
Precise date of Construction	÷	
Completion	:	
Subsequent changes	:	
Destruction / Demolition	:	

6. Ownership / Level of Protection

SINGLE /MULTIPLE :

:
:
:
:
:
:

7. Association

• WITH EVENTS In History : Living temple In Rituals : In Building Construction : Any other (specify) : WITH PERSONS Patron : Architect / Engineer : Any other (specify) :

8. Statement of Significance

Architectural
Archaeological
Historical
Religious
Any other (specify)

Temple having dome on the top.

9.	9. Physical Description and Decorative Features				
•	Context Urban / Rural Setting Surroundings		* Drawings (Attach extra sheet if necessary)		
	Surroundings		Stand in Isolation Integral part of a Landscape / Street / Complex		
•	Quantification Area Dimension (L x B x H)	:	(m / cm/ feet / inch)		
	Number of Blocks Number of Storys	:	01 01		
•	Spatial Organization Orientation Plan Allocation of Spaces	:	The Temple is oriented east/west and faces the east.		
<u>A</u> F	RCHITECTURAL STYLE				
•	Ornamentation Exteriors Interiors Movable Collections	:	Painted pillars and domes. Ritualistic objects		
Ar	y Other (specify)	:			

SECTION II: DESCRIPTION

10. Construction Technology

Indo-Persian Arcuate system Stone and Bricks.

11. Condition Assessment

In General

Good √/ Fair

✓ Siệ Se

Sign of Deterioration Serious Deterioration Danger of Disappearance

In Brief (Attach extra sheet if necessary):

Stains on the wall, floor is dirty.

12. Threats to the Property

✓ Natural
 Negligence
 Vandalism
 Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS