

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/PGT-148 **SECTION I: IDENTIFICATION** 1. Name Present Unknown Well Past Other Name (if any): 2. Location **LONGITUDE** 74°78'E **LATITUDE** 24°03'N Address Near Kila, Pratapgarh Village (village code) **Post**: Pratapgarh **District**: Pratapgarh State: Rajasthan **PIN:** 312605 Approach The Well is situated near by Kila in Pratapgarh district. It is 3km away from Pratapgarh bus stand. It is well connected by regular bus services. 3. Property Type Religious structures **Other Structures Buildings** Palace Temple Wall Fort Mosque Gateway Citadel Minar Pillar Others (specify) Govt. building Church Railway station Monastery Defence building Stupa Industrial building Tomb, Mausoleum Other public buildings Residential building Engineering structure Open space and related Note: it is a deep well cladeed structures with stone and plaster. Initially Iron wheel has been fitted for Bridge Public square Park or garden fetching the water. It is full of Tunnel water. Other engineering structure Graveyard ✓ Baolis, Well Tank

Cave

4. Property Use			
	ABANDONED√/ IN USE		
	:		
Present	: Source of water		
Past	: Source of water		
5. Age (Source)			
PERIOD	: 18th century AD		
YEARS	:		
Precise date of Construction	:		
Completion	:		
Subsequent changes	:		
Destruction / Demolition	:		
6. Ownership / Level of Protection	on		
SINGLE /MULTIPLE :			
Public: Archaeological Survey of	:		
India / State Archaeology	•		
Department / Any Other (Please			
specify)			
Private			
Any other (Please specify)	:		
Name	:		
Address	:		
Phone	:		
7. Association			
WITH EVENTS			
In History			
In Rituals	•		
In Building Construction	•		
Any other (specify)	•		
WITH PERSONS	•		
Patron			
Architect / Engineer	•		
Any other (specify)	•		
Any other (specify)	•		
8. Statement of Significance			
Architectural	Dilapidated Masonic structure.		
Archaeological	·		
Historical			
Religious			
Any other (specify)			

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features

Context
 Urban / Rural Setting
 Surroundings

* **Drawings** (Attach extra sheet if necessary)

Stand in Isolation

Integral part of a Landscape / Street / Complex

Quantification

Area Dimension (LxBxH):

(m / cm/ feet / inch)

Number of Blocks : 01 Number of Storys : 01

Spatial Organization

Orientation : The Temple is oriented east/west and faces the west.

Plan

Allocation of Spaces :

ARCHITECTURAL STYLE

Ornamentation

Exteriors Interiors

Movable Collections :

Any Other (specify) :

10. Construction Technology

Structural System : Rectangular Pillar made up of stone

Building Techniques : Masonry work Material of Construction : Stone, Metal

11. Condition Assessment

In General Good √/ Fair

✓ Sign of Deterioration

Serious Deterioration

✓ Danger of Disappearance

In Brief (Attach extra sheet if necessary):

Dilapidated

12. Threats to the Propert	12.	Threats	to the	Pro	pert
----------------------------	-----	----------------	--------	-----	------

✓ Natural
✓ Negligence
✓ Vandalism
Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
1017144107 11400	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
10. Maps/1 lans/2/awnigs	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTO	COMMENTS
COMMENTS	COMMENTS