

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/SIR-088 **SECTION I: IDENTIFICATION** 1. Name **Present** Chhag Bawari **Past** Other Name (if any): 2. Location LONGITUDE 73° 10' E LATITUDE 27⁰ 17['] N **Address** Near- Chhag Bawari Sagi Ki was bus stand, Sirohi. Village (village code) Sirohi Post: Sirohi District: Sirohi State: Rajasthan **PIN**: 307001 **Approach** The Bawari is situated at Sirohi City. It is 100 mt. away from Sirohi bus stand. It is well connected by regular bus service. 3. Property Type **Buildings** Religious structures **Other Structures** Palace Temple Wall Mosque Fort Gateway Citadel Minar Pillar Church Others (specify) Govt. building Railway station Monastery Bawari Defence building Stupa Industrial building Tomb, Mausoleum Other public buildings Residential building Engineering structure Open space and related Note: This multi storied step well structures has down ward staircases lead to the water. It has pillars with Bridge Public square Park or garden brackets. It has strong projection. Tunnel Other engineering structure Graveyard Baolis, Well Tank

Cave

4. Property Use	
	ABANDONED / IN USE: Abandoned
Present	<u>:</u>
Past	•
5. Age (Source)	
PERIOD	: 18 th Century AD
YEARS	:
Precise date of Construction	:
Completion	:
Subsequent changes	:
Destruction / Demolition	:
6. Ownership / Level of Protection	on
	SINGLE /MULTIPLE :
Public: Archaeological Survey of	:
India / State Archaeology	
Department / Any Other (Please	
specify)	
Private	:
Any other (Please specify)	:
Name	:
Address Phone	:
Filone	•
7. Association	
WITH EVENTS	
In History	: Step well
In Rituals	:
In Building Construction	:
Any other (specify)	:
 WITH PERSONS 	
Patron	:
Architect / Engineer	:
Any other (specify)	:
8. Statement of Significance	
✓ Architectural	
Archaeological	
Historical	
Religious Any other (specify)	Step well with staircases
Any other (specify)	Otop won with standases

SECTION II: DESCRIPTION

9.	Physical Description and D	ecora	ative Features
Context Urban / Rural Setting Surroundings			* Drawings (Attach extra sheet if necessary) Urban
Surroundings		Stand in Isolation Integral part of a Landscape / Street / Complex	
•	Quantification Area Dimension (L x B x H)	:	(m / cm/ feet / inch)
	Number of Blocks Number of Storys	:	01 04
•	Spatial Organization Orientation Plan Allocation of Spaces	: : :	The Bawari is oriented East-West and faces the East
•	Ornamentation Exteriors Interiors Movable Collections y Other (specify)	: : :	Pillars
10	. Construction Technology		
	Structural System Building Techniques Material of Construction	:	Multi storied step well with staircase Trabeate system Stone, plaster
11.	Condition Assessment		
		Sood Sood	/ Fair
	Sign of Deterioration Serious Deterioration Danger of Disappearance		
In	Brief (Attach extra sheet if	nece	ssary):

12. Threats to the Property	
	Natural Negligence Vandalism Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS