



# INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, [www.ignca.gov.in](http://www.ignca.gov.in)

## Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/SIR-105

### SECTION I : IDENTIFICATION

#### 1. Name

Present : Champa Bai Bawari  
 Past :  
 Other Name (if any):

#### 2. Location

LONGITUDE 73° 10' E

LATITUDE 27° 17' N

#### Address

Near Rajmata Dharamshala, Behind of Petrol Pump, Sirohi

: **Village (village code)** Sirohi  
**Post** : Sirohi **District:** Sirohi  
**State** : Rajasthan **PIN:** 307001

#### Approach

: The Bawari is situated at Sirohi City. It is 2 km. away from Sirohi bus stand. It is well connected by regular bus service.

#### 3. Property Type

##### **Buildings**

- Palace
- Fort
- Citadel
- Govt. building
- Railway station
- Defence building
- Industrial building
- Other public buildings
- Residential building

##### **Religious structures**

- Temple
- Mosque
- Minar
- Church
- Monastery
- Stupa
- Tomb, Mausoleum

##### **Other Structures**

- Wall
- Gateway
- Pillar
- Others (specify)  
**Bawari**

##### **Engineering structure**

- Bridge
- Tunnel
- Other engineering structure

##### **Open space and related structures**

- Public square
- Park or garden
- Graveyard
- Baolis, Well
- Tank
- Cave

**Note:** This is three storeyed step well built in famous Rajasthani cross section step pattern. It has nicely decorated bracket based pillar in a frame pattern.

#### 4. Property Use

---

**ABANDONED / IN USE :** Abandoned

**Present** :  
**Past** :

#### 5. Age (Source)

---

**PERIOD** : 17<sup>th</sup> Century AD  
**YEARS** :  
**Precise date of Construction** :  
**Completion** :  
**Subsequent changes** :  
**Destruction / Demolition** :

#### 6. Ownership / Level of Protection

---

**SINGLE /MULTIPLE :**

**Public** : Archaeological Survey of India / State Archaeology Department / Any Other (Please specify) :  
**Private** :  
**Any other (Please specify)** :  
**Name** :  
**Address** :  
**Phone** :

#### 7. Association

---

- **WITH EVENTS**
  - In History** :
  - In Rituals** : Rajasthani traditional step well
  - In Building Construction** :
  - Any other (specify)** :
- **WITH PERSONS**
  - Patron** : Champa Kanwar Iderachi W/o. Maharaw Surtan Singh
  - Architect / Engineer** :
  - Any other (specify)** :

#### 8. Statement of Significance

---

- |                                     |                     |                                     |
|-------------------------------------|---------------------|-------------------------------------|
| <input checked="" type="checkbox"/> | Architectural       |                                     |
| <input type="checkbox"/>            | Archaeological      |                                     |
| <input type="checkbox"/>            | Historical          |                                     |
| <input type="checkbox"/>            | Religious           |                                     |
| <input type="checkbox"/>            | Any other (specify) | Step well cross section staircases. |

## SECTION II: DESCRIPTION

### 9. Physical Description and Decorative Features

---

- **Context**  
**Urban / Rural Setting**  
**Surroundings**  
**\* Drawings** (Attach extra sheet if necessary)  
Urban  
  
**Stand in Isolation**  
**Integral part of a Landscape / Street / Complex**
  
- **Quantification**  
Area Dimension ( L x B x H) :  
(m / cm/ feet / inch)  
  
Number of Blocks :  
Number of Storys :
  
- **Spatial Organization**  
Orientation : The Bawari is oriented North-South and faces the East  
Plan :  
Allocation of Spaces :

### ARCHITECTURAL STYLE

- **Ornamentation**  
Exteriors : Waterbody  
Interiors :  
Movable Collections :  
**Any Other** (specify) :

### 10. Construction Technology

---

- Structural System** : Rajasthan cross section step based well
- Building Techniques** : Trabeate system
- Material of Construction** : Stone, plaster

### 11. Condition Assessment

---

**In General**                      **Good / Fair**  
Fair

- Sign of Deterioration
- Serious Deterioration
- Danger of Disappearance

**In Brief (Attach extra sheet if necessary):**

Decrepit.

## 12. Threats to the Property

---

- |                                     |                 |
|-------------------------------------|-----------------|
| <input checked="" type="checkbox"/> | Natural         |
| <input type="checkbox"/>            | Negligence      |
| <input type="checkbox"/>            | Vandalism       |
| <input type="checkbox"/>            | Urban Pressures |

### **SECTION III: REFERENCES**

#### **13. Reference Sources** (published and unpublished textual details)

---

#### **14. Photographs**

---

(attach list as in page 6, in case of multiple photographs)

**Photo Reference**

**CAPTION**

#### **15. Audio / Video**

---

(related to rituals / performance / festivals etc.)

**Reference**

**DESCRIPTION**

#### **16. Maps/Plans/Drawings**

---

#### **17. Listers**

---

**NAME**

**NAME**

#### **18. Reviewers**

---

**NAME**

**NAME**

**COMMENTS**

**COMMENTS**