

1. Name

Janpath, New Delhi -110 001, www.ignca.gov.in


Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/SIR-152

SECTION I: IDENTIFICATION

Present Past Other Name (if any):	: Mahaveer Swami Jain Mandir :	
2. Location		
LONGITUDE 73 ⁰ 10 ['] E	LATITUDE 27 [°] 17 [′] N	
Address	Bamanusar jee Sirohi Road, Sirohi	
	: Village (village code) Sirohi Post : Veerwara District: Sirohi State : Rajasthan PIN: 307022	
Approach	: The Temple is situated at Bawanwar jee in Sirohi. It is 17 km. away from Sirohi district. It is well connected by regular bus service.	

3. Property Type



4. Property Use

		ABANDONED / IN USE : In use	
Present	:	Religious	
Past	:	Religious	
	•	Kongloud	
5. Age (Source)			
PERIOD		19 th Century AD	
YEARS	:		
Precise date of Construction			
Completion	:		
Subsequent changes			
Destruction / Demolition	:		
	-		
6. Ownership / Level of Protection			
		SINGLE /MULTIPLE :	
Public : Archaeological Survey of	:		
India / State Archaeology			
Department / Any Other (Please			
specify)			
Private	:		
Any other (Please specify)	:		
Name	:		
Address	:		
Phone	:		
7. Association			
WITH EVENTS			
In History	:		
In Rituals	:		
In Building Construction	:		
Any other (specify)	:		
WITH PERSONS			
Patron	:		
Architect / Engineer	:		
Any other (specify)			
8. Statement of Significance			
Architectural			
Archaeological			

Historical Religious Any other (specify)

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features			
Context Urban / Rural Setting Surroundings	* Drawings (Attach extra sheet if necessary) Urban Stand in Isolation Integral part of a Landscape / Street / Complex		
Quantification Area Dimension (L x B x H) Number of Blocks Number of Storys	: (m / cm/ feet / inch) :		
• Spatial Organization Orientation Plan Allocation of Spaces	The Temple is oriented North-South and faces the North		
ARCHITECTURAL STYLE • Ornamentation Exteriors Interiors Movable Collections Any Other (specify)	 Domical superstructure rest on a carved stone pillars and pilasters. : 		

10. Construction Technology

Structural System	:	Indo-Persian
Building Techniques	:	Arcuate as well as Trabeate
Material of Construction	:	Stone and plaster etc.

11. Condition Assessment


In General	Good / Fair	
	Good	

Sign of Deterioration Serious Deterioration Danger of Disappearance

In Brief (Attach extra sheet if necessary):

Well maintained

12. Threats to the Property



SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS