

1. Name

Janpath, New Delhi -110 001, www.ignca.gov.in


Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/SIR-167

SECTION I : IDENTIFICATION

Present Past Other Name (if any):	: Shri Jiwit Mahaveer Swa : :	mi Jee Mandir
2. Location		
LONGITUDE 73 ⁰ 10 [°] E	LATITUDE 27 ⁰ 17 ['] N	
Address	Nandia Jiwit Swami, Jain Ma	ndir Sirohi
	: Village (village code) Post : Nandia State : Rajasthan	District: Sirohi PIN: 307022
Approach	•	t Jain Mandir Nandia in Sirohi. m Sirohi district. It is well s service.

3. Property Type



4. Property Use

		ABANDONED / IN USE : In use
Present		Religious
Past	:	Religious
	•	i tongiouo
5. Age (Source)		
PERIOD	-	17 th Century AD
YEARS	:	
Precise date of Construction	:	
Completion	:	
Subsequent changes	:	
Destruction / Demolition	:	
	•	
6. Ownership / Level of Protection	on	
		SINGLE /MULTIPLE :
Public : Archaeological Survey of	:	
India / State Archaeology	•	
Department / Any Other (Please		
specify)		
Private	:	
Any other (Please specify)	:	
Name	:	
Address	:	
Phone	:	
7. Association		
WITH EVENTS		
In History	:	
In Rituals	:	
In Building Construction	:	
Any other (specify)	:	
WITH PERSONS		
Patron	:	
Architect / Engineer	:	
Any other (specify)	:	
8. Statement of Significance		
Architectural		
Archaeological		

Historical Religious Any other (specify)

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features				
•	Context Urban / Rural Setting Surroundings		* Drawings (Attach extra sheet if necessary) Rural Setting Surroundings Stand in Isolation Integral part of a Landscape / Street / Complex	
•	Quantification Area Dimension (L x B x H) Number of Blocks Number of Storys	:	(m / cm/ feet / inch) 01 01	
•	Spatial Organization Orientation Plan Allocation of Spaces	:	The Temple is oriented East-West and faces the East	
•	RCHITECTURAL STYLE Ornamentation Exteriors Interiors Movable Collections by Other (specify)	: :	Series of curvilinear shikhars with multi angular pillars. Highly decorated, sanctum has lavishly carvings on marble	

10. Construction Technology

Structural System	:	Nagara style
Building Techniques	:	Trabeate
Material of Construction	:	Stone

11. Condition Assessment


In General	Good / Fair	
	Good	

Sign of Deterioration Serious Deterioration Danger of Disappearance

In Brief (Attach extra sheet if necessary):

Well maintained

12. Threats to the Property



SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS