

Other engineering structure

Janpath, New Delhi -110 001, www.ignca.gov.in

#### Documentation format for Archaeological / Heritage Sites / Monuments

#### Serial No.: RJ/SIR-170

#### **SECTION I : IDENTIFICATION** 1. Name Present Riksheshwar Mahadev Mandir 2 Past 2 Other Name (if any): 2 2. Location LONGITUDE 73<sup>0</sup> 10<sup>'</sup> E LATITUDE 27<sup>0</sup> 17<sup>'</sup> N Address Near- Jain Mandir Sirohi Village (village code) : Post: Nandia District: Sirohi State : Rajasthan **PIN:** 307022 Approach The Temple is situated at Nandia in Sirohi. It is 30 km. 2 away from Sirohi district. It is well connected by regular bus service. 3. Property Type **Other Structures Buildings Religious structures** Palace Temple Wall Fort Mosque Gateway Minar Pillar Citadel Govt. building Church Others (specify) Railway station Monastery Defence building Stupa Industrial building Tomb, Mausoleum Other public buildings Residential building Engineering structure Open space and related Note: This is a large temple established inside a large cave. It structures can be approached through staircase. The sanctum in shrines Bridae Public square Park or garden Tunnel a Shiv Lingam and Shiva family.

Graveyard Baolis, Well Tank Cave

## 4. Property Use

Archaeological Historical

Religious Any other (specify)

		ABANDONED / IN USE : In use		
Present	:	Religious		
Past	:	Religious		
5. Age (Source)				
PERIOD	:	10 <sup>th</sup> Century AD		
YEARS	:			
Precise date of Construction	:			
Completion	:			
Subsequent changes Destruction / Demolition	:			
Destruction / Demonition	•			
6. Ownership / Level of Protection				
		SINGLE /MULTIPLE :		
Public : Archaeological Survey of	:			
India / State Archaeology				
Department / Any Other (Please				
specify)				
Private	:			
Any other (Please specify)	:			
Name Address	:			
Phone	:			
Thone	•			
7. Association				
WITH EVENTS				
In History	:			
In Rituals	:			
In Building Construction	:			
Any other (specify)	:			
WITH PERSONS     Patron				
Architect / Engineer	:			
Any other (specify)	:			
····, ····· (-p····)/	-			
8. Statement of Significance				
Architectural				

# **SECTION II: DESCRIPTION**

9. Physical Description and Decorative Features				
Ŭ	Context Jrban / Rural Setting Surroundings		<ul> <li>* Drawings (Attach extra sheet if necessary)</li> <li>Rural Setting Surroundings</li> <li>Stand in Isolation</li> <li>Integral part of a Landscape / Street / Complex</li> </ul>	
Â	Quantification Area Dimension (L x B x H) Number of Blocks Number of Storys	:	(m / cm/ feet / inch) 01 01	
C P	Spatial Organization Drientation Plan Allocation of Spaces	: : :	The Temple is oriented East-West and faces the East	
• C E Ir M	HITECTURAL STYLE Drnamentation Exteriors Interiors Novable Collections Other (specify)	::	Well managed staircase	

## **10. Construction Technology**

#### 11. Condition Assessment

In General	Good / Fair	
	Good	

Sign of Deterioration Serious Deterioration Danger of Disappearance

### In Brief (Attach extra sheet if necessary):

Well maintained

## 12. Threats to the Property

✓ Natural
 Negligence
 Vandalism
 Urban Pressures

# **SECTION III:** REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	(attach list as in page 6, in case of multiple photographs
Photo Reference	(
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS