


Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/SIR-176

SECTION I : IDENTIFICATION 1. Name Present Baleshwar Mahadev jee Mandir 2 Past 2 Other Name (if any): 2 2. Location LONGITUDE 73⁰ 10['] E LATITUDE 27⁰ 17['] N Address Baleshwar Hanuman Mandir Sirohi Road, Sirohi Village (village code) : Post : Sirohi District: Sirohi State : Rajasthan **PIN: 307001** Approach The Temple is situated at Sirohi road in Sirohi. It is 6 2 km. away from Sirohi district. It is well connected by regular bus service.

3. Property Type



4. Property Use

		ABANDONED / IN USE : In use
Present Past	:	Religious Religious
5. Age (Source)		
PERIOD YEARS Precise date of Construction Completion Subsequent changes	::	18 th Century AD
Destruction / Demolition	:	
6. Ownership / Level of Protection	on	
		SINGLE /MULTIPLE :
Public : Archaeological Survey of India / State Archaeology Department / Any Other (Please specify)	:	
Private	:	
Any other (Please specify)	:	
Name Address	÷	
Phone	:	
	•	
7. Association		
WITH EVENTS		
In History	:	
In Rituals	:	
In Building Construction Any other (specify)	•	
WITH PERSONS	•	
Patron	:	
Architect / Engineer	:	
Any other (specify)	:	
8. Statement of Significance		

Architectural Archaeological Historical Religious Any other (specify)

SECTION II: DESCRIPTION

9.	9. Physical Description and Decorative Features			
•	Context Urban / Rural Setting Surroundings		 * Drawings (Attach extra sheet if necessary) Rural Setting Surroundings Stand in Isolation Integral part of a Landscape / Street / Complex 	
•	Quantification Area Dimension (L x B x H) Number of Blocks	:	(m / cm/ feet / inch) 01	
•	Number of Storys Spatial Organization Orientation Plan Allocation of Spaces	:	01 The Temple is oriented North-South and faces the South	
•	RCHITECTURAL STYLE Ornamentation Exteriors Interiors Movable Collections by Other (specify)	: :	Domical mandapam and curvilinear sanctum	

10. Construction Technology

		Nagara style Trabeate Stone, plaster
--	--	--

11. Condition Assessment

In General	Good / Fair Good	
	Good	

Sign of Deterioration Serious Deterioration Danger of Disappearance

In Brief (Attach extra sheet if necessary):

Maintained

12. Threats to the Property

✓ Natural
 Negligence
 Vandalism
 Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS