

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/SIR-197 **SECTION I: IDENTIFICATION** 1. Name **Present** Bhelo Shankar jee Mandir **Past** Other Name (if any): 2. Location LONGITUDE 73⁰ 10['] E LATITUDE 27⁰ 17 N **Address** Near Nakki Lake Mount Abu, Sirohi Village (village code) Post: Mount Abu District: Sirohi State: Rajasthan **PIN**: 307501 **Approach** The temple is situated at Mount Abu in Sirohi. It is 85 km. away from Sirohi district. It is well connected by regular bus service. 3. Property Type Religious structures **Other Structures Buildings** Temple Wall Palace Fort Mosque Gateway Pillar Citadel Minar Govt. building Church Others (specify) Railway station Monastery Defence building Stupa Industrial building Tomb, Mausoleum Other public buildings Residential building Engineering structure Open space and related Note: This is a temple dedicated to Lord Shiva. It is built in Nagara structures style. It has painted façade. The Bridge Public square mukh mandapam has domical Park or garden Tunnel superstructure. The garbhgriha Other engineering structure Gravevard has curvilinear shikhara decorated Baolis, Well anshikhara topped Tank aamalak and kalash. The sanctum Cave inshrines a Shiv Lingam flanked

by Nag Devata. Renovation work has been done in recent work,

| 4. Property Use | | | | | |
|---|-----------------------------|---|--|--|--|
| | ABANDONED / IN USE: In us | e | | | |
| Present Past | Religious Religious | | | | |
| 5. Age (Source) | | | | | |
| PERIOD YEARS Precise date of Construction Completion Subsequent changes Destruction / Demolition | 18 th Century AD | | | | |
| | | | | | |
| 6. Ownership / Level of Protection | SINGLE /MULTIPLE : | | | | |
| Public: Archaeological Survey of India / State Archaeology Department / Any Other (Please specify) Private Any other (Please specify) Name Address Phone | SINGLE/MIGETILE : | | | | |
| WITH EVENTS In History In Rituals In Building Construction Any other (specify) WITH PERSONS Patron Architect / Engineer Any other (specify) | Living temple | | | | |
| 8. Statement of Significance Architectural Archaeological Historical Religious Any other (specify) | | | | | |

SECTION II: DESCRIPTION

| 9. P | 9. Physical Description and Decorative Features | | | | |
|--|---|---------------------|---|--|--|
| Context Urban / Rural Setting Surroundings | | | * Drawings (Attach extra sheet if necessary) Urban | | |
| | | | Stand in Isolation Integral part of a Landscape / Street / Complex | | |
| | Quantification Area Dimension (L x B x H | H) : | (m / cm/ feet / inch) | | |
| | Number of Blocks Number of Storys | : | 01 01 | | |
| | Spatial Organization Orientation Plan Allocation of Spaces | : : : | The temple is oriented East – West and faces the East | | |
| • | CHITECTURAL STYLE Ornamentation Exteriors Interiors Movable Collections / Other (specify) | : | Curvilinear shikhara | | |
| 10. | Construction Technology | у | | | |
| | Structural System Building Techniques Material of Construction | : : : | Nagara style Trabeate Stone, bricks and plaster | | |
| 11. | Condition Assessment | | | | |
| | In General | Good Good | / Fair | | |
| | Sign of Deterioration Serious Deterioration Danger of Disappearance | e | | | |
| In E | Brief (Attach extra sheet i | f neces | ssary): | | |
| Wel | Il maintained | | | | |

| 12. Threats to the Property |
|--|
| ✓ Natural Negligence Vandalism Urban Pressures |

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

| 14. Photographs | |
|-------------------------|--|
| | (attach list as in page 6, in case of multiple photographs |
| Photo Reference | |
| CAPTION | |
| 15. Audio / Video | |
| | (related to rituals / performance / festivals etc.) |
| Reference | |
| DESCRIPTION | |
| 16. Maps/Plans/Drawings | |
| | |
| | |
| 17. Listers | |
| NAME | NAME |
| 18. Reviewers | |
| NAME | NAME |
| COMMENTS | COMMENTS |