


Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/SIR-204

SECTION I: IDENTIFICATION 1. Name Present Chamunda Mata Mandir 2 Past 2 Other Name (if any): 2 2. Location **LONGITUDE** $73^{\circ} 10^{\circ} E$ LATITUDE 27⁰ 17['] N Address Achalgarh, Mount Abu, Sirohi Village (village code) : Post: Mount Abu District: Sirohi State: Rajasthan PIN: 307501 Approach The Temple is situated at Achalgarh Mount Abu in 2 Sirohi. It is 90 km. away from Sirohi district. It is well connected by regular bus service.

3. Property Type



4. Property Use

		ABANDONED / IN USE : In use		
Present		Religious		
Past		Religious		
	•			
5. Age (Source)				
PERIOD		16 th Century AD		
YEARS				
Precise date of Construction	;			
Completion	:			
Subsequent changes	:			
Destruction / Demolition	:			
6. Ownership / Level of Protection				
		SINGLE /MULTIPLE :		
Public : Archaeological Survey of	:			
India / State Archaeology				
Department / Any Other (Please				
specify)				
Private	:	Devsthan Vibhag Board Sirohi/Rajasthan		
Any other (Please specify)	:			
Name	:			
Address	:			
Phone	:			
7. Association				
WITH EVENTS				
In History	:			
In Rituals	:			
In Building Construction	:			
Any other (specify)	:			
WITH PERSONS				
Patron	:			
Architect / Engineer	:			
Any other (specify)	:			
8. Statement of Significance				
Architectural	_			
Archaeological				
Historical				

Historical Religious Any other (specify)

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features			
•	Context Urban / Rural Setting Surroundings		* Drawings (Attach extra sheet if necessary) Rural setting surrounds Stand in Isolation Integral part of a Landscape / Street / Complex
•	Quantification Area Dimension (L x B x H) Number of Blocks Number of Storys	:	(m / cm/ feet / inch) 01 01
•	Spatial Organization Orientation Plan Allocation of Spaces	:	The Temple is oriented North – South and faces the South
•	RCHITECTURAL STYLE Ornamentation Exteriors Interiors Movable Collections by Other (specify)	: :	Toran Door

10. Construction Technology

Structural System	:	Indo Persion
Building Techniques	:	Arcuvate And Wellear Trabeate
Material of Construction	:	Stone And Plaster

11. Condition Assessment


In General	Good / Fair	
	Good	

Sign of Deterioration
Serious Deterioration
Danger of Disappearance

In Brief (Attach extra sheet if necessary):

Weakening of stone, Cheeping of surface etc.

12. Threats to the Property



SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS