


Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/SIR-209

SECTION I: IDENTIFICATION 1. Name Present Kunthu Nath Jain Mandir 2 Past 2 Other Name (if any): 2 2. Location **LONGITUDE** 73⁰ 10['] E LATITUDE 27⁰ 17['] N Address Achalgarh, Mount Abu, Sirohi Village (village code) : Post: Mount Abu District: Sirohi State: Rajasthan PIN: 307501 Approach The Temple is situated at Achalgarh Mount Abu in 2 Sirohi. It is 90 km. away from Sirohi district. It is well connected by regular bus service. 3. Property Type



4. Property Use

| | | ABANDONED / IN USE : In use |
|--|----|-----------------------------|
| Present | : | Religious |
| Past | : | Religious |
| 5. Age (Source) | | |
| | | |
| PERIOD | : | 18 th Century AD |
| YEARS | : | |
| Precise date of Construction | : | |
| Completion | : | |
| Subsequent changes Destruction / Demolition | ÷ | |
| Destruction / Demonition | • | |
| 6. Ownership / Level of Protection | on | |
| | | SINGLE /MULTIPLE : |
| Public : Archaeological Survey of | : | |
| India / State Archaeology | | |
| Department / Any Other (Please | | |
| specify) | | |
| Private | : | |
| Any other (Please specify) Name | ÷ | |
| Address | : | |
| Phone | : | |
| | • | |
| 7. Association | | |
| WITH EVENTS | | |
| In History | : | |
| In Rituals | : | |
| In Building Construction | : | |
| Any other (specify) | : | |
| WITH PERSONS | _ | |
| Patron Architect / Engineer | ÷ | |
| Any other (specify) | : | |
| Any other (specify) | • | |
| 8. Statement of Significance | | |
| | | |
| | | |

Architectural Archaeological Historical Religious Any other (specify)

SECTION II: DESCRIPTION

| 9. Physical Description and Decorative Features | | | |
|---|--|-----|--|
| • | Context Urban / Rural Setting Surroundings | | * Drawings (Attach extra sheet if necessary) Rural settings surroundings Stand in Isolation Integral part of a Landscape / Street / Complex |
| • | Quantification Area Dimension (L x B x H) Number of Blocks Number of Storys | : | (m / cm/ feet / inch) 01 01 |
| • | Spatial Organization Orientation Plan Allocation of Spaces | : | The temple is oriented East – West and faces the West |
| • | RCHITECTURAL STYLE Ornamentation Exteriors Interiors Movable Collections by Other (specify) | : : | Ornated pillars and parapet |

10. Construction Technology

| Structural System | : | Nagara style |
|--------------------------|---|-------------------|
| Building Techniques | : | Trabeate |
| Material of Construction | : | Stone and plaster |

11. Condition Assessment

| In General | Good / Fair | |
|------------|-------------|--|
| | Good | |

Sign of Deterioration Serious Deterioration Danger of Disappearance

In Brief (Attach extra sheet if necessary):

Well maintained.

12. Threats to the Property

✓ Natural
 Negligence
 Vandalism
 Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

| 14. Photographs | |
|-------------------------|---|
| | (attach list as in page 6, in case of multiple photographs) |
| Photo Reference | |
| CAPTION | |
| 15. Audio / Video | |
| | (related to rituals / performance / festivals etc.) |
| Reference | |
| DESCRIPTION | |
| 16. Maps/Plans/Drawings | |
| | |
| 17. Listers | |
| NAME | NAME |
| 18. Reviewers | |
| NAME | NAME |
| COMMENTS | COMMENTS |