


INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/SIR-284

SECTION I : IDENTIFICATION 1. Name			
Present Past Other Name (if any):	: Boys Hostel :		
2. Location			
LONGITUDE 73 ⁰ 10 ['] E	LATITUDE 27 ⁰ 17 ['] N		
Address	Abu Road, Sirohi		
Approach		District: Sirohi PIN: 307026 at Abu Road in Sirohi. It is 70 District. It is well connected by	
3. Property Type			
BuildingsPalaceFortCitadelGovt. buildingRailway stationDefence buildingIndustrial buildingOther public buildingsResidential building	Religious structuresTempleMosqueMinarChurchMonasteryStupaTomb, Mausoleum	Other Structures Wall Gateway Pillar Others (specify)	
Engineering structure	Open space and related	Note: It is a massive Masonic	



4. Property Use ABANDONED / IN USE : In use Present Hostel 2 Past : Shikargah 5. Age (Source) 19th Century A.D. (Early 19th Century) PERIOD 2 YEARS : Precise date of Construction 2 Completion 2 Subsequent changes : **Destruction / Demolition** : 6. Ownership / Level of Protection SINGLE /MULTIPLE : **Public** : Archaeological Survey of : Govt. of Rajasthan India / State Archaeology Department / Any Other (Please specify) Private 2 Any other (Please specify) : Name : Address 2 Phone ÷ 7. Association WITH EVENTS In History : In Rituals 2 In Building Construction : Any other (specify) : WITH PERSONS Patron 2 **Architect / Engineer** 2 Any other (specify) : 8. Statement of Significance Architectural Archaeological Historical Religious Any other (specify)

SECTION II: DESCRI

9. Physical Description and Decorative Features			
	Context Urban / Rural Setting Surroundings		* Drawings (Attach extra sheet if necessary) Urban Stand in Isolation Integral part of a Landscape / Street / Complex
	Quantification Area Dimension (L x B x H) Number of Blocks Number of Storys	: : :	(m / cm/ feet / inch) 01
	Spatial Organization Orientation Plan Allocation of Spaces	:	The Hostel is oriented east-west and faces the east
•	CHITECTURAL STYLE Ornamentation Exteriors Interiors Movable Collections Tother (specify)	:	Ribbed dome with inverted lotus type of pinnacle.

10. Construction Technology

Building Techniques : Are	lo-Persian cuate as well as Trabeate one, bricks and plaster
---------------------------	--

11. Condition Assessment

In General	Good / Fair Fair		
Cign of Deterioretion			

Sign of Deterioration
Serious Deterioration
Danger of Disappearance

In Brief (Attach extra sheet if necessary):

Blackening of surface, discoloration etc.

12. Threats to the Property

✓ Natural
Negligence
Vandalism
Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS