



Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: ARCH/ASS/GHT/006**SECTION I: IDENTIFICATION****1. Name ()**

Present

Rajapukhuri

Past

Other Name (if any)

2. Location ()

Address

LONGITUDE E 93° 53' 114" LATITUDE N 26° 17' 235"

State

AssamVillage (village code) No 1 Debarani gram.Post _____ District Lalaghat.

PIN _____

Approach

3. Property Type ()**Buildings**

- Palace
 Fort
 Citadel
 Govt. building
 Railway station
 Defence building
 Industrial building
 Other public buildings
 Residential building

Engineering structure

- Bridge
 Tunnel
 Other engineering

Religious structures

- Temple
 Mosque
 Minar
 Church
 Monastery
 Stupa
 Tomb, Mausoleum

Open space and related structures

- Public square
 Park or garden
 Graveyard
 Baolis, Well

Other Structures

- Well
 Gateway
 Pillar
 Others (specify)

structure

- Tank
- Cave

4. Property Use ()

ABANDONED / IN USE

Present

Tank is dried and trees are grown on it

Past

Tank

5. Age (Source) ()

PERIOD ()

YEARS ()

Precise date of

Construction

Completion

Subsequent changes

Destruction / Demolition

Lower limit is 12th century AD.

6. Ownership / Level of Protection ()

SINGLE / MULTIPLE

Public Archaeological Survey of India / State Archaeology Department / Any Other (Please specify) Community

Private

Any other (Please specify)

Name

Address

Phone

7. Association ()

• WITH EVENTS

✓ History

In Rituals

In Building Construction

Any other (specify)

• WITH PERSONS

Patron

Architect / Engineer

Any other (specify)

8. Statement of Significance ()

- Architectural
- Archaeological
- Historical
- Religious
- Any other (specify) _____

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features

● Context

* Drawings (Attach extra sheet if necessary)

Urban / Rural Setting
Surroundings

Stand in Isolation
Integral part of a Landscape / Street / Complex

● Quantification

Area Dimension (L x B x H)

5 Bighas 13 Lokhas presently.
_____ (m / cm / feet / inch)

Number of Blocks

Number of Storeys

● Spatial Organization

Orientation

Plan

Rectangular

Allocation of Spaces

ARCHITECTURAL STYLE

● Ornamentation

Exteriors

NA

Interiors

NA

Movable Collections

* Any Other (specify)

Remnants of brick wall noticed nearby.

10. Construction Technology

Structural System

Building Techniques

NA

Material of Construction _____

11. Condition Assessment

In General

Good / Fair

- Sign of Deterioration
- Serious Deterioration
- Danger of Disappearance

In Brief (Attach extra sheet if necessary)

The tank is completely dried and covered with big big trees. The distance of the tank is only remaining in the lower level and eye evidence of the older ones.

12. Threats to the Property

- Natural
- Negligence
- Vandalism
- Urban Pressures